

Wareham Historical Society Historic Building Survey

October 21, 2013



Great Neck Union Chapel
Old District School No. 6
Old Methodist Meeting House
Fearing Tavern Museum
Captain Kendrick House



DURLAND ■ VAN VOORHIS

po box 1169
mattapoisett, ma
02379
t 508.993.6567
dvvarchitects.com





TABLE OF CONTENTS

	Section	Page
	Table of Contents	1
	Acknowledgments	3
	Preface	4
Part I	Executive Summary	
	Executive Summary	6
	Project Cost Summary	11
	Possible Funding Opportunities	12
	Partial Repair Chronology	13
Part II	Great Neck Union Chapel	
	Architectural Survey	15
	Drawings	21
	Project Cost Estimate	23
	Annual Maintenance Plan	24
Part III	Old District School No. 6	
	Architectural Survey	26
	Drawings	30
	Project Cost Estimate	32
	Annual Maintenance Plan	33
Part IV	Old Methodist Meeting House	
	Architectural Survey	35
	Drawings	41
	Project Cost Estimate	44
	Annual Maintenance Plan	45
Part IV	Fearing Tavern Museum	
	Architectural Survey	47
	Drawings	52
	Project Cost Estimate	60
	Annual Maintenance Plan	61
Part V	Captain Kendrick House	
	Architectural Survey	63
	Drawings	69
	Project Cost Estimate	75
	Annual Maintenance Plan	76



TABLE OF CONTENTS

Appendices	Page
A Structural Report by Boston Building Consultants	77
B Great Neck Union Chapel Photographs	85
C Great Neck Union Chapel – Miscellaneous Articles & Images	92
D Old District School No 6 Photographs	99
E Old District School No 6 – Miscellaneous Articles & Images	105
F Old Methodist Meeting House Photographs	109
G Old Methodist Meeting House – Miscellaneous Articles & Images	116
H Fearing Tavern Museum Photographs	123
I Fearing Tavern Museum – Miscellaneous Articles & Images	135
J Captain Kendrick House Photographs	161
K Captain Kendrick House – Miscellaneous Articles & Images	176
L National Park Service Preservation Brief 47 Maintaining Small & Medium Sized Historic Buildings	181



APPENDIX A – STRUCTURAL REPORT BY BOSTON BUILDING CONSULTANTS

B O S T O N B U I L D I N G C O N S U L T A N T S

241 A St., Suite 220, Boston, MA 02210

6 1 7 / 5 4 2 - 3 9 3 3

F a x 6 1 7 / 4 2 6 - 8 9 2 2

June 20, 2013

Mr. Charlie Van Voorhis
Durland and Van Voorhis Architects
PO Box 1169
Mattapoisett, MA 02739

Re: Structural Assessment
Five (5) Wareham Historical Buildings
Wareham, MA

BBC Job #13052.00

Dear Charlie,

At your request on May 31, 2013, I visited five (5) historic buildings in Wareham, MA to inspect the as-built construction for signs of structural distress, damage and concerns. My investigations were limited to elements that were visible at the time of my visit and accessible. Following are my observations, conclusions and recommendations for each of the five (5) properties:

GREAT NECK UNION CHAPEL

General Building Description:

The Chapel is a single story wood framed building that was moved to the current location and supported by a new concrete foundation. The building has a hipped roof over the rear end and a gable roof over the remaining footprint. There is a full basement under the chapel and no access under the floor or above the ceiling of the front entrance. The exposed foundation is a cast in place concrete foundation wall to grade and granite block from grade to the first floor level. The first floor is framed with wood joists spanning left to right (when facing the entrance) supported by the exterior foundation walls and an intermediate wood beam. The wood beam is supported by a series of steel pipe columns. The basement floor appears to be a ground supported concrete slab.

Structural Observations, Conclusions & Recommendations:

1. The concrete basement slab and perimeter foundation walls appear to be structurally sound and free of signs of distress or settlements; therefore, we do not anticipate the need for new structural reinforcements.
2. The 1st floor framing under the seating area is 2x6 joists, spaced 24" on center; spanning approximately 7'-6" continuous over a 6x6 beam support at mid-span of the chapel. The joists are notched 4" at the foundation wall and at the center wood beam support. Horizontal splitting at the ends of several joists was noted. The floor framing under the rear stage area and the front 6 ft. of the main hall are 2x8's spaced at 24" o.c.; spanning the full width (15 ft) of the building..

The current floor (live) load for an assembly area (Chapel) with movable seating is 100 psf (not including the material self weights) and 60 psf for assembly areas with fixed seating. The as-built floor construction will require new structural reinforcements for either load case, but fewer reinforcements will be required for the fixed seating scenario. Following are recommendations for both cases:

B O S T O N B U I L D I N G C O N S U L T A N T S

Fixed Seating (60 psf Live Load)

- Connect each existing 2x6 joist to the foundation wall sill plates and to the intermediate 6x6 wood beam with new metal joist hangers sized for the appropriate floor loading.
- Add a new wood beam at mid-span (in line with the existing 6x6 wood beam) of the 2x8 floor joist under the rear and the front 6 ft.
- Connect each existing 2x8 joist to the foundation wall sill plates and to the new intermediate wood beam with new metal joist hangers sized for the appropriate floor loading.
- Install solid wood blocking between each joist at the centerline of the existing 6x6 and the new wood beam.

Moveable Seating (100 psf Live Load)

- Reinforce the center 6x6 wood beam with a new 2x10 LVL beam each side of the in place beam.
- Install a new (3) 2x10 LVL beam at mid span of the rear 2x8 joists and mid span of the 2x8 joists in the front 6 ft.
- Prior to reinforcing the existing wood beam; the existing joists must be temporarily shored to permit cutting the joists for the installation of the new LVL's.
- Install new hangers at each end of each joist.
- Sister every other 2x6 and 2x8 floor joist with a new 2x6 LVL.
- Connect each new 2x6 LVL to the foundation wall sill plate and the new reinforced intermediate beam with metal joist hangers sized for the appropriate loading.

3. The bulkhead door is severely deteriorated and fell apart when I opened it. I suggest the opening be secured immediately to prevent access to the basement and suggest rebuilding the bulkhead door to fit the existing bulkhead opening.

4. The exterior side walls of the Chapel are noticeably out of square and not plumb. There is evidence of cracking on the interior walls and ceiling finishes that is indicative of movement of the exterior walls. As noted from a small ceiling hatch, the ceiling / attic joists are supported by the exterior wall and hung from the roof rafters. It appears that the attic / ceiling joists are nailed into the side of the wall studs, e.g. below the wall top plate and not directly connected to the roof rafters. Several of the attic / ceiling joists are not continuous (e.g. one piece from side wall to side wall).

The attic was not easily accessible, but from a view through the ceiling hatch it appears that the roof structure is not properly tied at the eave level to resist the horizontal thrust of the sloped roof rafters. The lack of adequate ties has resulted in the horizontal movement of the exterior walls and may have resulted in cracking of the wall finishes.

It will be difficult and costly to straighten and plumb the exterior walls; however, I suggest installing new ties at the eave level to reduce the possibility of future lateral movement, damage, etc. The new ties could be steel rods or wood joists provided the ties are continuous (one piece) from eave to eave and a properly connected to the ends of the rafters.

B O S T O N B U I L D I N G C O N S U L T A N T S

OLD METHODIST MEETING HOUSE

General Building Description:

The Meeting House is a single story wood framed building with a basement. According to documentation in the Meeting House, the structure was moved to its current location and a rear addition was added for a kitchen, and accessibility. The roof is gable structure. The façade is wood clapboards. The basement is a dirt floor with limited height and accessibility.

Structural Observations, Conclusions & Recommendations:

1. The foundation wall of the original building appears to be a stone wall while the rear addition has a cast in place concrete wall. There were no obvious signs of cracking of the foundation or the interior wall finishes that would be indicative of ongoing foundation settlements. Therefore, it appears that the foundation is adequately serving its current use.
2. The first floor is framed with wood joists supported by the perimeter foundation walls and intermediate wood beams. It appears the original floor joist and floor sheathing was removed, the original support beams left in place, a new ledger installed along each side of the original wood beams; new joists installed and connected with metal hangers to the new ledgers and new plywood sheathing placed over the new joists.

There is evidence of decay in the original wood beams due to water and insect infestation; therefore, I suspect that the original floor joists and sheathing were removed due to rot and decay from water and insect infiltration. It's not clear why the original wood beams were retained, but I suspect that they were evaluated and deemed to be structurally sound.

Accurately measuring and analyzing the as-built floor structure is beyond the scope of this report and would require selective demolition to expose existing conditions and to access all areas of the framing. However, based on my limited observations, I have the following structural concerns:

- The attachment of the new ledger to the original wood beam.
- The extent of damage to the original wood beams.
- The metal joist hanger connections to the ledgers.

At the very least I suggest all joist hangers be inspected and all hanger nail holes filled and a qualified Exterminator periodically inspect and treat any signs of ongoing active insect infestation. Also, I suggest any signs of movement (e.g. sagging floors, cracking wall or ceiling finishes, doors and windows that no longer function, etc.) be reported to a Professional to investigate the floors for structural issues and ongoing movement.

3. The roof is a gable structure with a vaulted ceiling and periodic steel tie rods across the meeting house ceiling to resist the horizontal thrust of the roof rafters. A noticeable sag in the roof is evident from the exterior. I attempted to access the area of the sagging roof from the attic and noticed broken roof sheathing and a dip in the roof, but I was unable to access the eave or the tie rod locations for a close inspection. According to Charlie and as evidence by an uprooted tree stump, a tree recently fell on the roof in the area in question. It's unclear how the roof was repaired, but the sag is still evident. The stability of the roof structure cannot be

B O S T O N B U I L D I N G C O N S U L T A N T S

accurately evaluated without selective demolition of the finishes; however, there were no obvious signs of structural distress (e.g. cracking wall and ceiling finishes, etc.) other than the roof sag noted previously. I suggest the roof and ceiling and wall finishes be inspected periodically for signs of movement and any evidence of movement be reported to a qualified Professional for further investigation.

4. I noted the wood clapboards close to the ground have signs of rot and decay due to the ground cover too close to the clapboard sheathing and the overgrown shrubs and plantings around the perimeter promoting a wet environment. The current conditions will at a minimum result in decay and rot of the clapboards and in the worst case create an attractive environment for insect infestation that could ultimately damage the building structure. The current extent of damage cannot be determined without further investigation and selective demolition. I suggest the plantings around the perimeter be removed, the ground cover lowered, the site graded so surface and roof downspout water will run away from the building. Also, I suggest the deteriorated clapboards be removed, the structure behind investigated for additional damage and all decayed material replaced with new materials.
5. I noted damage to the exterior wooden fascia/crown at the roof eave that appears to be from an animal, rodent or possibly occurred from the tree accident. The hole appears to provide easy access to the attic for animals, rodents, water, insects, etc.. I suggest the attic be inspected by an Exterminator and all openings closed to inhibit access from animals, rodents, etc. that can ultimately cause damage to the building.

OLD DISTRICT SCHOOL #6

General Building Description:

The original Old School #6 built before 1825 is a wood framed one room single story building with two additions, one on each gable end, added at a later date. The original building was moved to this site and is now bearing on concrete piers.

Structural Observations, Conclusions & Recommendations:

1. The first floor is framed over a crawl space. The wood joists are supported by perimeter and interior wood beams that are supported by a series of concrete piers. Access to the floor framing was not accessible; however, from an access hole in one location of the perimeter skirt board, the framing appeared to be free of decay or rot and the concrete piers appeared to have been located in some organized fashion. Due to limited access, a general analysis and close inspection of the existing floor framing was not possible. However, the floors appeared to be relatively sound with no obvious soft areas and relatively level; however, it appears from my limited perspective that some of the floor joists were not bearing on the wood beams. I suggest all of the joists be inspected and shims added to ensure the joists are bearing solid on the intermediate wood beams.

B O S T O N B U I L D I N G C O N S U L T A N T S

2. The gable roof structure of the original school house and the two additions appears to have been conventionally framed with rafters and ties at the eave elevation. The roofs, walls and ceilings do not appear to have any obvious signs of structural distress. Therefore, I don't anticipate the need for new structural reinforcements.
3. The exterior paint is peeling, most likely due to moisture trapped in the wood clapboards. The current condition does not appear to have affected the building structure; however, extended inadequate protection of the exterior siding can ultimately lead to deterioration of the building structure.

FEARING TAVERN

The Fearing Tavern, dating to the 1600's, is a two story building with an accessible attic and a partial basement. The floor beyond the basement is an inaccessible crawl space. A close inspection of the building structure to identify specific areas of concern is not possible due to the interior historic finishes and limited access. However, following are several general structural concerns and observations noted during my inspection.

1. The building appears to be a post beam structure whereby the building was constructed as a skeleton of posts, beams and diagonal cross bracing. Once the skeleton was complete the floors and walls were built within the skeleton.
2. The basement is limited to a small area in the front of the building. The basement was damp and the wood framing had signs of insect infestation and decay due to moisture. The framing noted in the basement has undergone various reinforcements and changes.
3. I noted a sag in the 2nd floor / 1st floor ceiling. My investigation to determine the cause for the sag was limited due to finishes, but it appears that a past fire and a stair case in this area may have caused damaged that required altering the building structure.
4. Typically in a post and beam structure the posts are uninterrupted from the roof to the foundation. However, in my attempt to follow the posts I noted a window at the first floor interrupting the posts and in another place an interior posts could not be tracked.
5. The Fearing Tavern has most likely undergone numerous changes, renovations, repairs, fires, water and insect infiltration, damage, etc. over the course of its 400 + years. A structural analysis of the as-built construction would require extensive demolition and removal of the finishes which is not possible and beyond the scope of this investigation. However, I suggest the following items that are evident and of current concern be addressed:
 - All overgrown plantings be cut down to expose the exterior to reduce the possibility of future decay due to moisture and insect infestation.
 - The gutters appear to have been taken off the house. I suggest a drainage bed and possibly a perforated pipe be installed around the perimeter to collect and dispose of surface and roof rainwater off site.
 - A basement drainage system with a sump and ventilation system be considered in the basement to reduce the moisture levels and reduce the possibility of future rot and decay due to water and insect infestation.
 - An Exterminator inspect and treat the property periodically to inhibit insect and rodent infestation.

B O S T O N B U I L D I N G C O N S U L T A N T S

- I suggest the sag in the 2nd floor be investigated further by a qualified Contractor who can selectively remove and replace interior historic finishes and determine the cause of the sag and possible repairs.

CAPTAIN JOHN KENDRICK MARITIME MUSEUM

The Captain John Kendrick Museum is a two story wood framed building built in 1745 as a private residence. It appears that a single story addition was added a later date. The main residence has two floors, an accessible attic and a full basement while the single story addition is built over an inaccessible crawl space. Following are my observations and recommendations to address general structural issues for areas that were visible and accessible.

1. The floors, walls and roof structure have undergone movements and settlements over the 170 year life of the building. Some of the settlements may be due to questionable soil conditions and dimensional changes of the building framing, but these conditions would have occurred soon after construction and most likely were not the main cause of the observed settlements.
2. The main house perimeter foundation wall and the center chimney / floor support structure have been reinforced with new cast in place concrete. I suspect that water infiltration damaged the original building foundations, creating an unstable condition and a need for new reinforcements. Also, the basement was very damp, mold was evident and there were signs of past insect infestation and damage to the existing wood framing. I suspect that replacement of foundation sill plates, wall framing, and other decayed framing was required and performed during the foundation reinforcements. Most likely these conditions were the primary cause of noticeable settlements.
3. Assuming the cause for the settlements has been addressed and repaired, I suggest the basement carpet / flooring be removed, an under slab drainage system with a sump and a ventilation / dehumidification system be installed to reduce the high level of humidity and moisture in the basement. Also, the floors, roof, ceilings, and walls should be inspected periodically for signs of ongoing movement, e.g. cracking finishes, poorly functioning doors or windows,, etc. and report any suspected issues to a qualified professional for further investigation.
4. The exterior clapboards, shingles, trim, etc. are in need of attention and repair. I noted holes in the trim along the roof eave that allow animals, rodent, insects, water, etc. easy access into the interior. Also, the plantings around the perimeter are overgrown, creating a wet environment that promotes rot and decay due to moisture and insect infestation.

I suggest all plantings and ground cover around the perimeter be trimmed, all damage and rotted materials replaced, all holes repaired and the exterior siding scrapped and painted to prevent deterioration and reduce the possibility of decay due to water infiltration. Also, I suggest a drainage bed and possibly a perimeter perforated pipe be installed around the building perimeter to collect and discharge surface water and roof runoff away from the building foundations.

B O S T O N
B U I L D I N G
C O N S U L T A N T S

5. The first floor framing is a combination of original framing members and reinforcements added a later date. It appears that posts, joists and beams have been added throughout the 1st floor framing most likely to address concerns as they arose. Evidence of insect infestation was evident; therefore, I suspect that the new supports may have been added to address decayed members.

I suggest a qualified Exterminator inspect the property on a periodic basis for signs of active insect infestation and treat the property as required reducing the possibility of infestation. Also, I suggest a qualified Contractor / Carpenter review the as-built framing to make specific recommendations for permanent supports to replace the as-built temporary members.


6. I noted several original roof rafters have been reinforced with new rafters sistered along side the existing decayed members. The existing members appeared to be infested with insects and fresh wood powder was evident on the attic floor directly under the members in question.

A structural analysis of the as-built framing and new reinforcements is beyond the scope of this review and inspection. However, as noted previously, I suggest a qualified Exterminator inspect the roof framing on a periodic basis for signs of active insect infestation and treat the property as required reducing the possibility of infestation. Also, I suggest any members found to be infested with insects or decayed due to rot, fungus or mold be removed, disposed off site and replaced with new members of an equivalent size and strength.

This concludes the structural observations noted during my visit along with my conclusions and recommendations. The preceding observations and recommendations are based on the structural elements that were clearly visible and easily accessible at the time of my visit and did not include any demolition or selective removal of any finishes. If you have any questions, comments or require clarifications please call.

Sincerely,

BOSTON BUILDING CONSULTANTS



Daniel J. Platcow, P.E.
Vice President

Jobs / 13052/WarehamHistSoc DJP/dp



APPENDIX B – GREAT NECK UNION CHAPEL PHOTOGRAPHS




2013-05-23 10.15.5...



2013-05-23 10.15.54...



2013-05-23 10.16.0...



2013-05-23 10.16.1...



2013-05-23 10.16.1...



2013-05-23 10.16.2...



2013-05-23 10.16.3...



2013-05-23 10.16.4...




2013-05-23 10.16.4...



2013-05-23 10.16.5...



2013-05-23 10.16.5...




2013-05-23 10.17.0...




2013-05-23 10.17.2...



2013-05-23 10.17.4...



2013-05-23 10.17.51...



2013-05-23 10.17.51...



2013-05-23 10.17.5...



2013-05-23 10.18.0...



2013-05-23 10.18.1...



2013-05-23 10.18.4...



2013-05-23 10.18.5...



2013-05-23 10.19.0...



2013-05-23 10.19.1...



2013-05-23 10.19.2...




2013-05-23 10.19.4...



2013-05-23 10.20.1...



2013-05-23 10.20.1...



2013-05-23 10.32.3...



2013-05-23 10.32.4...



2013-05-23 14.27.0...



2013-05-23 14.27.2...



2013-05-23 14.27.2...




2013-05-23 14.27.3...



2013-05-23 14.27.4...



2013-05-23 14.27.5...



2013-05-23 14.28.0...



2013-05-23 14.28.2...



2013-05-23 14.28.2...



2013-05-23 14.28.3...



2013-05-23 14.28.4...



2013-05-30 09.20.2...



2013-05-30 09.20.2...



2013-05-30 09.21.1...



2013-05-30 09.21.3...



2013-05-30 09.21.4...




2013-05-30 09.22.0...



2013-05-30 09.22.0...




2013-05-30 09.47.0...



5-30-13 007.jpg



5-30-13 008.jpg



5-30-13 009.jpg



5-30-13 010.jpg



5-30-13 011.jpg



5-30-13 012.jpg



5-30-13 013.jpg



5-30-13 014.jpg



5-30-13 015.jpg



5-30-13 016.jpg



5-30-13 017.jpg



5-30-13 018.jpg



5-30-13 019.jpg



5-30-13 020.jpg



5-30-13 021.jpg



5-30-13 022.jpg



5-30-13 023.jpg



5-30-13 024.jpg



5-30-13 025.jpg



5-30-13 026.jpg



5-30-13 027.jpg




5-30-13 028.jpg



5-30-13 029.jpg




5-30-13 030.jpg



5-30-13 031.jpg



5-30-13 032.jpg



2013-06-17 09.48.4...



2013-06-17 09.49.1...




2013-06-17 09.49.3...



2013-06-17 09.49.4...



2013-06-17 09.49.5...



2013-06-17 09.50.2...



2013-06-17 09.50.4...



2013-06-17 09.51.0...



2013-06-17 09.51.2...




2013-06-17 09.51.5...



2013-06-17 09.52.2...



2013-06-17 09.52.2...



2013-06-17 09.52.5...



2013-06-17 09.53.5...



2013-08-29 09.31.1...



2013-08-29 09.37.4...



2013-08-29 09.38.5...



2013-08-29 09.39.0...



2013-08-29 09.39.2...



2013-08-29 09.39.4...



2013-08-29 09.40.0...



2013-08-29 09.42.0...



2013-08-29 09.43.0...



2013-08-29 09.43.3...



2013-08-29 09.43.4...



2013-08-29 09.44.1...



2013-08-29 09.48.4...



2013-08-29 09.49.0...




2013-09-04 12.28.2...



APPENDIX C – GREAT NECK UNION CHAPEL - MISCELLANEOUS ARTICLES & IMAGES


The Chapel



by Sara W. and Hildy W.

The Union Chapel was built around 1880. Originally it stood on Great Neck Road. The Union Society purchased a one-room schoolhouse and moved it to stand beside its chapel. The buildings have been restored to their original condition and stand together on Main Street, across from the town green. The Chapel can be rented for weddings or other events. Contact Mrs. Betty Wright, Curator, at (508) 295-3227 for more information.

The Captain John Kendrick Maritime Museum



Captain Kendrick's home is owned and operated by the Wareham Historical Society as a museum honoring the maritime history of the town. It is a gambrel roofed Cape style house with a center chimney and a "good morning" stairway. Built circa 1745, it contains original paneling and early wallpapers.

On display, you will find furnishings dating from the 18th and 19th centuries, Maritime paintings by local artist Charles Sidney Raleigh who lived briefly in the house, and a model of the Schooner "Ernestina". The "Ernestina" served for many years as a packet ship, sailing between the United States and the Cape Verde Islands. Textiles and costumes of the era also form a part of the museum's collection.


Captain Kendrick gained prominence during the American Revolutionary War when he commanded several Privateers in the Patriot cause. While serving as captain of the "Fanny" he successfully captured two vessels of the British Jamaican fleet in Biscay Bay.

Captain Kendrick came home to Wareham where he purchased a house and wharf from David Nye in 1778.



Kendrick was chosen to lead an expedition to China via the Northwest Coast in 1787 for a group of Boston businessmen. This expedition gave the United States an entrance into the lucrative China Trade for tea, silks and ceramics by trading furs obtained from Native Americans in the area of present day Washington and Oregon. His ships were the "Columbia Rediviva" and the sloop "Lady Washington".

The expedition was instrumental in the exploration and acquisition of the vast Oregon Territory for the U.S. and also the discovery of the Columbia River which was named for the ship "Columbia". Captain Kendrick was the first



American to attempt trade with Japan. Captain Gray of Tiverton, R.I. who was his second in command was the first to carry the American flag around the world.

WAREHAM HISTORICAL SOCIETY FORM

Name(s) _____

Address _____

City _____ State _____ Zip _____

Day phone _____

Even phone _____

Membership Dues: Individual \$16 \$

Family \$25 \$

Lifetime \$250 \$

Donations: I wish to make a tax deductible gift of \$ _____

I would like more information about including the Wareham Historical Society in my estate planning.

I wish to be contacted about making a gift of documents, books, furniture, or real estate to the Society.

Publications: "The Fearing and the Fearing Tavern" by Raymond Ryder @ 10 \$ _____

"Life and Times in Wareham Over 200 Years 1739-1939" by Raymond Ryder @ \$20 \$ _____

TOTAL INCLUDED \$ _____

*Recent financial reports and tax exemption letter for the Wareham Historical Society are available for review by writing us at the address below.

Mail to:
WAREHAM HISTORICAL SOCIETY, INC.
P.O. Box 211
Wareham, MA 02571

The One Room Schoolhouse




The Schoolhouse was built in 1825 and was used for 100 years. A kitchen was added in Victorian times by the Union Chapel Association of Great Neck while they owned the building.

The Chapel

The Union Chapel, circa 1880, rests next to the schoolhouse.

The Chapel and Meetinghouse are available for weddings and other special events.




The Old Methodist Meetinghouse

The Meetinghouse was built in 1835 and is now used by the Historical Society for it's meetings. Across the green (center park) you can see the First Congregational Church founded the same year as the town, in 1739.

Travel a mile down Main Street to visit the Captain John Kendrick Maritime Museum across the street from the beautiful Mary Besse Park in the Narrows Historic District on Wareham's waterfront.

During the War of 1812, on July 13, 1814 British Marines from the H.M.S. Nimrod came ashore under a flag of truce and proceeded to march down Main Street burning the ships in the harbor and in William Fearing's Shipyard. They set a cotton factory on fire with Congreve rockets and took 12 citizens hostage before returning to sea.



THE FEARING TAVERN MUSEUM

Open

July and August

Thursday thru Sunday 1-4

(with guided tours)

Also open by appointment.

Call Betty Wright at 508-295-3227

THE CAPTAIN JOHN KENDRICK MARITIME MUSEUM

Open

July and August

Saturday and Sunday 1-4

(with guided tours)

Also open by appointment.

Call Betty Wright at 508-295-3227


Wareham is located in Southeastern Massachusetts and is easily reached from Routes 195, 495, 25, 6, and 28.

The Fearing Tavern Museum


The Tavern, restored in 1958, is located in Wareham, Massachusetts where the Wampanoag Indian Agawam Trail from Plymouth crossed the Wankinco (Wareham) River.

The building contains portions built in 1690, 1765, and 1820. Sixteen period rooms contain authentic 18th and 19th century furnishings, toys, tools, and many decorative and useful objects. The major portion of the Georgian Colonial house with it's white clapboarded facade was built by tavern keeper **Benjamin Fearing** in 1765 and it remained in the Fearing family for over 200 years. It retained the earlier house his father Israel Fearing had purchased from Isaac and Elizabeth Bump (or Bumpas) in 1747.

Isaac operated a grist mill and lived in this 1690 house after the conclusion of King Phillip's War made it safe to live in the area. In Isaac's four room house, citizens met to conduct business and made their plans to create the town of Wareham, which was incorporated in 1739. Benjamin's son, Benjamin Haskell Fearing added a new kitchen and bedroom wing in the 1820's.



The One Room Schoolhouse




The Schoolhouse was built in 1825 and was used for 100 years. A kitchen was added in Victorian times by the Union Chapel Association of Great Neck while they owned the building.

The Chapel

The Union Chapel, circa 1880, rests next to the schoolhouse.

The Chapel and Meetinghouse are available for weddings and other special events.



THE FEARING TAVERN MUSEUM

Open 10

July and August

Thursday thru Sunday 1-4

(with guided tours)

Also open by appointment

Call Betty Wright at 508-295-9221

THE CAPTAIN JOHN KENDRICK MARITIME MUSEUM

Open 10

July and August

Saturday and Sunday 1-4

(with guided tours)

Also open by appointment

Call Betty Wright at 508-295-9221

Wareham is located in Southeastern Massachusetts and is easily reached from Routes 195, 495, 25, 6, and 28

Wareham Coeries, Wareham, Mass.

l of proposed Wareham historic district

n a knoll overlooking Broad Marsh, the Prince Burgess house on East Wareham, and the ambrel-roofed Kendrick house on Lower Main St. There are also the society buildings on Great Neck Rd.—the District 6 schoolhouse, the Union Chapel. Historic spotting could protect them, Mr. Rider suggests.

The committee met last month, and after hearing Mr. Rider's outline of the monument square area

as an historical district, approved the plan. Atty. Decas read the law regarding establishing an historic district, and he was charged with drafting a letter, in compliance with the law, regarding the Wareham plan, to the Massachusetts Historical Commission; the commissioner of Commerce and the commissioner of Natural Resources.

At the present time the Wareham committee will concentrate on the monument square plan, which encompasses that area of town which was the original Wareham center area. Spot zoning is not being ruled out as a future development. It is doubtful that the plan will be ready in time for March town meeting, Mr. Rider states.


In the short ten years of its existence, the society has raised the funds to bring the Fearing Tavern to its nearly complete restoration. With only work on the main roof, the west wall and the wing at the back, remaining to be done, the building, when completed will have cost \$45,000 to restore. In addition to attracting many historically minded visitors, it has been toured by many Wareham school children, winning a new generation of citizens interested in preserving their town's history.

With the completion of the Fearing Tavern, the society will not be without projects to work on. Sitting in the woods next to Mary Wing Park, is their next project.


The Thacher house has been moved two times before it

reached its present site. Originally where the Roland Thatcher House is now, it was moved across the street when the nursing home was built. The original brickwork in the chimneys and fireplaces were lost in this move. The society was offered the building by the Duns, and, at a cost of \$5,000 moved it to its present location. Fill is now being dumped around its new foundation.

Mr. Rider estimates that \$5,000 will put the building in a better condition. It will then be open for viewing during the summer season. Furnishings would prove no problem, he says. "People are always calling up asking for antiques to use." This is a demonstration, he explains, of how firmly the society is now established.



A HOUSE THAT BLEW ITS top—this house, which is located in the proposed district, is probably basically very old; however, it suffered the fate of many a well-kept house—it was renovated. In this case, a whole new story was put on it, and its oldtime lines were lost.




MEM of the riding—The rich within essence of then probal build- restoration. be done is wing. In-

side this 1690 building is revealed ample evidence of its involvement in the Revolutionary war, its use as a stage stop, selectmen's meeting place, post office, and, originally, the simple home of miller Isaac Bump. It is the gift to the Historical Society, of Mr. and Mrs. Ernest Blanchard. When work on it is completed, \$45,000 will have been spent on its restoration.



AMONG THE HOMES in the monument area which are nearly 200 years old is the Raymond A. Riders'. Historical Society president, Mr. Rider (shown here) proposes that a Wareham historic district should center around this area, including not only the homes here, but also, of course the Society's Fearing Tavern and Thacher house. The latter, a gift of Mr. and Mrs. William A. Dunn, now awaits restoration on its new site next to Mary Wing park.



clothing, to a ment table was bright with cloth with the singing of "Silent Night" returned from and napkins in a holiday motif, to a guitar accompaniment by tea, and to the tall red candles, and the colorful Mrs. Carignan.

October 24, 1938

Preservation of history is go

The Historical Society, Florence S. Otike, and Society of the Old Wareham Historical District, President Raymond A. Ridder, have come to the aid of the town, and last building construction and remodeling, with the exception of the district are limited in any effort to preserve the appearance of a period in the past. Proposals for building or remodeling permits must not only go to the building inspector (and gas, wiring, etc. if necessary) but also to the


Historic District Committee, for their approval of the changes.

Such districts have been established in many New England towns, as well as elsewhere in the U.S. They are generally believed to increase land values and attractiveness. Present structures in the district are not effected by the district, except if their owners want to change them. Then changes must conform to the district regulations as interpreted by the committee.


On the day the old Courier building was torn down, we felt a little nostalgic, and with Historical Society, president, Ray Rider, went for a tour of the area which has been over the years considered for a Wareham historic district. Exclusive of the business buildings in the area, the district would include the buildings around monument square, the Fearing Tavern and the Thacher house, the Tremont Nail Co. and the buildings up Main St. to Mackie's Bridge.

Many of the private homes in this area approach 200 years in age; others have historic interest. Key to the area are the Society's Fearing Tavern and Thacher house. Also included are the old town office—now the "Rec" center, the adjacent town-owned parking area, and the Congregational Church and parsonage.


However, all the interesting and historic buildings in Wareham are not confined to these few streets. Among the many others that Mr. Rider finds worth protecting would be the old Bates house which sits



OLD DISTRICT SCHOOLHOUSE, with the adjacent Union Chapel, located on Great Neck Road at Crooked River, are historic buildings the society protects. Only about 60 years old, according to Society's President Ray Rider, the buildings represent a time and way of life that has rapidly faded. The buildings are now occasionally used for society meetings; however, three times recently vandals broke in and caused damage. The chapel, a gift of Ethel H. Burgess, is a special project of hers.



MACKIE'S HOUSE, one of the town's house next to two of the other large colonials in the proposed district. The houses, with imprinted with the names of former owners, are kept in proud condition by today's owners. The name also designates the bridge over the railroad a few yards further along Main Street. Mr. Bartholomew was one of the superintendents of the local iron mills; he went into cranberries.




WHAT WILL ALWAYS BE Wareham Historical Society Fearing Tavern. This building's walls contain more of early American towns and probably any other surviving building, is within sight of com. The only major work remaining the main roof, west side and

Women's group enjoys

stant coffee and tea and moistened towlettes sent to a missionary family now on furlough from India; a quantity of dish towels for distribution (missionary f Chile, South building fund



APPENDIX D – OLD DISTRICT SCHOOL NO 6 PHOTOGRAPHS



2013-05-23 11.13.0...



2013-05-23 11.13.1...



2013-05-23 11.13.2...



2013-05-23 11.13.2...



2013-05-23 11.13.3...




2013-05-23 11.13.4...



2013-05-23 11.13.5...



2013-05-23 11.14.0...



2013-05-23 11.14.1...




2013-05-23 11.14.2...



2013-05-23 11.14.4...




2013-05-23 11.14.4...



2013-05-23 11.14.5...



2013-05-23 11.15.1...



2013-05-23 11.15.2...



2013-05-23 11.16.1...



2013-05-23 11.16.2...



2013-05-23 11.16.3...



2013-05-23 11.16.3...



2013-05-23 11.16.5...



2013-05-23 11.16.5...



2013-05-23 11.17.0...



2013-05-23 11.17.1...



2013-05-23 14.27.1...



2013-05-23 14.28.5...



2013-05-23 14.29.0...



2013-05-23 14.29.1...



2013-05-23 14.29.2...



2013-05-23 14.29.3...



2013-05-23 14.29.4...



2013-05-23 14.29.5...



2013-05-23.pdf



5-30-13 056.jpg



5-30-13 057.jpg



5-30-13 058.jpg



5-30-13 059.jpg



5-30-13 060.jpg



5-30-13 061.jpg



5-30-13 062.jpg



5-30-13 063.jpg




5-30-13 064.jpg



5-30-13 065.jpg



5-30-13 066.jpg



5-30-13 067.jpg



5-30-13 068.jpg




5-30-13 069.jpg



5-30-13 070.jpg



5-30-13 071.jpg



5-30-13 072.jpg



5-30-13 073.jpg



5-30-13 074.jpg



5-30-13 075.jpg




5-30-13 076.jpg



5-30-13 077.jpg



2013-06-17 09.57.1...



2013-06-17 09.57.3...



2013-06-17 09.57.5...



2013-06-17 09.59.0...



2013-06-17 09.59.3...



2013-06-17 10.00.3...



2013-06-17 10.02.0...



2013-06-17 10.02.0...



2013-06-17 10.02.2...



2013-06-17 10.02.4...




2013-06-17 10.02.5...



2013-06-17 10.02.5...



2013-06-17 10.03.1...



2013-06-17 10.03.2...



2013-06-17 10.03.4...



2013-06-17 10.04.1...



2013-06-17 10.04.2...



2013-06-17 10.04.3...



2013-06-17 10.04.4...



2013-06-17 10.05.1...



2013-06-17 10.05.3...



2013-06-17 10.06.1...



2013-06-17 10.10.4...



2013-06-17 10.10.4...



2013-08-26 10.43.1...



2013-08-26 10.44.0...



2013-08-26 10.44.2...



2013-08-29 09.22.1...



2013-08-29 09.23.2...



2013-08-29 09.23.3...



2013-08-29 09.24.4...



2013-08-29 09.25.0...



2013-08-29 09.25.0...



2013-08-29 09.25.5...




2013-08-29 09.26.1...



2013-08-29 09.26.3...



2013-08-29 09.27.1...



2013-08-29 09.27.2...



2013-08-29 09.27.3...




2013-08-29 09.31.10...



APPENDIX E – OLD DISTRICT SCHOOL NO 6 - MISCELLANEOUS ARTICLES & IMAGES

Old District
School No.
Built Before 1825



Welcome to the only remaining district schoolhouse in Wareham. It was known as District School No.6 or the Indian Neck School. It was built before 1825 and used as a school until June of 1920. Up to eight grades were taught by one teacher in the single classroom. The Union Chapel Association of Great Neck added a kitchen and cloakroom after they purchased it to be used for church suppers and other functions. The building was moved to Main Street, Wareham so that it could be preserved. It now stands between The Old Methodist Meetinghouse and The Chapel, two other buildings owned by the

Peek at the past

By RAYMOND RIDER

We often hear older people say, "Oh, for the good old days." The trouble with that expression is it ignores all problems of the good old days.

One remembers only the quiet subtleties of simple meals, simple pleasures, pleasant family evenings together. Most people who remember the good old days have put aside the 12-hour working day at a dollar a day, the long walk to the grocery store, hand-scrubbing the weekly laundry, interminable hours over the cooking stove, and other hands-on duties with the broom and dustmop.

Those were the days (1874) when Wareham had an almshouse on a lot purchased from Oliver Swift for \$300 and built by Charles F. Washburn for \$3,626 with a few extras such as stone work by W.W. Griffith for \$350 and other small items for a total of \$4,374.76. Every inmate in the almshouse was duly registered in the town report as well as any other person on relief.

Every vendor who furnished goods for any town purpose was also in the town reports. A list of resident and non-resident taxpayers was there with the amount of taxes each paid and also the industries then in business. The Franconia Iron and Steel Company paid \$1,226.75, for example, Tremont Nail Company paid \$1,909.90, Parker Mills, \$1,590.03, Wareham Nail Company, \$711.90 and Union Store Company, \$11.25.

The school committee members in 1874 were John M. Kinney, Galen Humphrey and Samuel B. Bumpus, and there were 11 district schools in operation. The Center School classes were so small that one teacher, Miss Nettie Sampson, was released and her class joined a senior group under Miss Abby Brett for the winter term. The

district schools had mixed grades 1-9 in their one-room buildings.

District School No. 6 was near the entrance to Agawam Beach when Miss Ruth F. Bourne taught there in 1874. Now the old schoolhouse, in its second moving, is near Center Park in what used to be District No. 1.

The "dog money" (dog tax) was used in this year for "apparatus for the high school" and the balance of \$161 was distributed among the district schools. Those were the "good old days!"

Raymond Rider is a founder and charter member of the Wareham Historical Society and currently serves on its board of directors.



Moving day

**District School No
of Raymond Rider**

past

district schools had mixed grades 1-9 in their one-room buildings.

District School No. 6 was near the entrance to Agawam Beach when Miss Ruth F. Bourne taught there in 1874. Now the old schoolhouse, in its second moving, is near Center Park in what used to be District No. 1.

The "dog money" (dog tax) was used in this year for "apparatus for the high school" and the balance of \$161 was distributed among the district schools. Those were the "good old days!"

Raymond Rider is a founder and charter member of the Wareham Historical Society and currently serves on its board of directors.




Moving day

District School No. 6, recently moved to District No. 1 (Photo courtesy of Raymond Rider)



APPENDIX F – OLD METHODIST MEETING HOUSE PHOTOGRAPHS



2013-05-23 11.48.2...



2013-05-23 12.01.5...



2013-05-23 12.01.5...



2013-05-23 12.01.5...



2013-05-23 12.02.0...




2013-05-23 12.02.1...



2013-05-23 12.02.1...




2013-05-23 12.02.1...



2013-05-23 12.02.2...




2013-05-23 12.02.3...



2013-05-23 12.02.3...



2013-05-23 12.02.5...



2013-05-23 12.02.5...



2013-05-23 12.03.0...



2013-05-23 12.04.0...



2013-05-23 12.04.09...



2013-05-23 12.04.5...



2013-05-23 12.05.0...



2013-05-23 12.05.0...



2013-05-23 12.05.1...




2013-05-23 12.05.2...




2013-05-23 12.05.4...



2013-05-23 12.05.5...



2013-05-23 12.05.5...



2013-05-23 12.06.2...




2013-05-23 12.08.0...



2013-05-23 12.08.2...



2013-05-23 12.08.3...



2013-05-23 12.08.4...



2013-05-23 12.08.5...



2013-05-23 14.29.4...



2013-05-23 14.29.5...



2013-05-23 14.30.0...



2013-05-23 14.30.1...



2013-05-23 14.30.2...



2013-05-23 14.30.3...



2013-05-23 14.30.4...



2013-05-23 14.30.5...



2013-05-23 14.31.0...



2013-05-23 14.31.1...



2013-05-23 14.31.2...



2013-05-23 14.31.2...



2013-05-23 14.31.3...



2013-05-23 14.31.4...



2013-05-23 14.31.5...



2013-05-23 14.32.0...



ContactSheet-001.pdf



5-30-13 033.jpg



5-30-13 034.jpg



5-30-13 035.jpg



5-30-13 036.jpg




5-30-13 037.jpg



5-30-13 038.jpg



5-30-13 039.jpg



5-30-13 040.jpg



5-30-13 041.jpg



5-30-13 042.jpg



5-30-13 043.jpg



5-30-13 044.jpg



5-30-13 045.jpg




5-30-13 046.jpg



5-30-13 047.jpg



5-30-13 048.jpg



5-30-13 049.jpg



5-30-13 050.jpg



5-30-13 051.jpg



5-30-13 052.jpg



5-30-13 053.jpg



5-30-13 054.jpg



5-30-13 055.jpg



2013-06-17 10.27.2...



2013-06-17 10.27.3...




2013-06-17 10.27.3...



2013-06-17 10.27.4...




2013-06-17 10.27.4...



2013-06-17 10.27.5...



2013-06-17 10.28.2...



2013-06-17 10.28.4...



2013-06-17 10.28.4...



2013-06-17 10.28.5...



2013-06-17 10.29.0...



2013-06-17 10.29.0...



2013-06-17 10.29.2...



2013-06-17 10.29.3...



2013-06-17 10.29.3...



2013-06-17 10.29.5...




2013-06-17 10.30.1...



2013-06-17 10.30.3...



2013-06-17 10.30.4...



2013-06-17 10.30.5...




2013-08-29 09.22.0...



2013-08-29 09.28.3...



2013-08-29 09.28.4...



2013-08-29 09.28.4...



2013-08-29 09.31.10...



2013-08-29 09.54.5...



2013-08-29 09.55.3...



2013-08-29 09.55.4...



2013-08-29 10.16.4...



2013-08-29 10.16.4...



2013-08-29 10.16.4...



2013-08-29 10.16.5...



2013-08-29 10.17.0...



2013-08-29 10.17.3...



2013-08-29 10.17.3...



2013-08-29 10.17.4...




2013-08-29 10.17.5...



2013-08-29 10.18.0...



2013-08-29 10.18.1...



2013-08-29 10.18.1...



2013-08-29 10.18.2...



2013-08-29 10.22.4...



2013-08-29 10.22.5...



2013-09-04 12.29.0...



2013-09-04 12.29.0...



2013-09-04 12.29.4...



APPENDIX G – OLD METHODIST MEETING HOUSE - MISCELLANEOUS ARTICLES & IMAGES


America's Coolest Recliner

- Storage arm cooler with snacks or a six-pack of



REMEMBERING WHEN

Parker Mills



Before restorations were begun in 1976, this little building, which was last used as a Laundromat, was the first Methodist church in Wareham. Standing across from Town Common at Parkers Mills, it was given to the Wareham Historical Society by Mr. and Mrs. Joseph Chamberlain of Rochester. If you have memories or photos of Wareham churches you would like to share with our readers please contact Sharon Desrosiers at 10 N. Main St., Fall River, MA 02720, or call 508-979-4404.

Standard-Times library photo

CHRONOLOGY

1811 Services held in homes sometime during 1811-1812

1812

1813

1814

1815

1816

1817

1819

1820

1821

1822

1823

1824

1825

1826

1827

1828

1829

1830 Pheneson Slocum, a Methodist Circuit rider, from the south, comes to Wareham.

1831 A meeting house is built on Tihonet Road during 1831-32. It was 28 feet square and cost \$1,000.00.

1832

1833

1834 No regular services are held during this year because of acts of violence against the Methodists.

1835 Methodist Meeting house is moved to the "Centre" where it was more secure from vandalism.

1836

1837

1838

1839

1840

1841 Seventy people are converted at a revival meeting held this year.

1842 First reference to an old Methodist traditional campmeeting under a tent was held. Quarterly meeting decides to build a new meeting house. When completed, it held fifty to sixty pews and cost approximately \$3,000.00

1843 January 6 - Plot of land on Main Street deeded to Trustees of the Methodist Episcopal Church for construction of church.

1844

1845

1846

1847

1848

1849

1850

1851

1852

1853

Church History 1811-2000

1854

1855

1856 **Records of the church are destroyed by an unknown person.**

1857

1858

1859

1860

1861

1862

1863

1864 **Because of differences of opinion, the Agawam Chapel (later East Wareham Methodist Church) was opened.**

1865

1866

1867

1868

1869

1870

1871

1872

1873

1874

1875

1876

1877

1878

1879

1880

1881

1882

1883

1884

1885

1886

1887

1888

1889

1890

1891

1892

1893

1894

1895

1896

1897

1898

1899

1900

1901

1902

1903 *Rev. H. Elmer*

Church History 1811-2000

1904	
1905	
1906	
1907	
1908	
1909	
1910	
1911	D. L. Jeffers
1912	
1913	
1914	
1915	
1916	
1917	
1918	
1919	
1920	
1921	
1922	
1923	
1924	
1925	William Schaffstall
1926	
1927	
1928	
1929	
1930	
1931	E. McP. Ames
1932	
1933	E. McP. Ames
1934	E. McP. Ames, pastor
1935	Ralph Seaver, pastor
There was a large youth group and young adults in the church	
1936	Ralph Seaver, Jr.
1937	Ralph Seaver Jr.
1938	George Andrews, pastor
1939	George Andrews
1940	George Andrews
1941	Loren W. Dow
1942	Loren W. Dow
1943	C. Wackley / Stanley E. Smith
1944	The original belfry was destroyed by a hurricane H. A. Stuart Stanley E. Smith
1945	
1946	H. A. Stuart
1947	George R. Walverton
1948	G. R. Walverton
1949	
1950	St. Frank Gulinello
1951	Belfry rebuilt. Gulinello
1952	Gulinello

1904-1905

2

Church History 1811-2000 -

1953 ~~Gerald C. Meecker~~ pastor Frank Gulinello, Sr

1954 August 31, Hurricane Carol does extensive damage to the church building causing it to be declared unsafe for use. The church met in the recreational building of the Congregational Church on Gibbs Avenue for one month. Then, due to the pastor leaving to attend school, the church joined with the Methodist Church in Marion until a new pastor was named.

1955 February - The Official Board appointed a building committee. Building plans from the Nelson Jacobs Associates of Boston were accepted by the congregation. The reconstruction and renovation was estimated to have a cost of \$25,000.00. Laminated arches were manufactured and shipped from Albert Lea, Minnesota. Summer services held at the Wareham Drive In Theater from May to September when inclement weather forced them to have services indoors. The Red Men offered their building for Sunday services and the American Legion provided shelter for the kindergarten which was the first public preschool with state certified instructors within the town of Wareham. The school was operated by the church for several years until the town assumed responsibility in accordance with state regulations.

1956 February 12 - rededication of the present church building. *James Knorr*

1957 *James M. Knorr*

1958 *Gerald L. Meecker*

1959 *Gerald L. Meecker*

1960 *Gerald L. Meecker*

1961

1962

1963

1964 The Sunday School is very large. An Army barracks is obtained, at no charge, from Otis Field to be converted to church school rooms. The generosity of Herman T. Gammons, along with others, made this addition possible. During the dedication on January 26, it was named the Gammons Room.

1965 *Thomas Barks*

1966

1967 *N.B. Pierce*

1968 *R. Sawtelle*

1969 *Earl B. Luscombe*

1970 *Earl B. Luscombe*

1971

1972

1973 Bruce Pehrson, pastor

1974

1975

1976

1977

1978

1979

1980

1981 Robert Kendall, pastor

1982

1983

Church History 1811-2000

1984 John Disburg, pastor

1985 In December a committee is named to provide access to the church sanctuary for the handicapped and elderly of the congregation.

1986 An elevator was installed making the sanctuary more accessible to the handicapped

1987 January 11, the congregation votes to seek "Strategic Parish" status thereby enabling the church to seek a pastor on a full-time basis. Rev. Jon Disburg was the pastor at this time.

1988 Rev. Marjorie Mollar is appointed pastor. Under her loving care and guidance, the church continued its growth.

1989

1990

1991

1992 June 4, rededication of newly renovated downstairs hall. It was decided to rename it Friendship Hall. A gift from the estate of Barbara Smith provided a great boost toward completion of this room.

1993

1994

1995

1996 In June the new steeple was lowered into place. This steeple replaces the one destroyed by Hurricane Carol in 1954.

1997 Elizabeth M. McClintock is appointed half-time pastor by the Conference.

1998

1999 A committee is formed to plan the refurbishing of the sanctuary. New carpeting is installed, the pews refinished to their 1850 condition and beauty. In October a service of rededication was held. The goal of \$15,000.00 was raised by the time the work was completed in late August. This extra-mile giving was in addition to oversubscribing the budget for the past two years! A generous gift from a benefactor made it possible to obtain a new sound system for the church

2000 Major repairs are made on the parsonage (mandated by state law, the Annual Conference guidelines for parsonages, and lack of attention during the past 5-6 years).

Pastor Liz and her family will be moving into the parsonage in May. July 1st of this year Pastor Liz McClintock was reappointed for her fourth year as pastor. In July of this year the congregation voted to construct a ramp into the building and install a new elevator chairlift making the sanctuary and Friendship Hall much more accessible to those less physically able

2001 The handicapped ramp and elevator chairlift is completed by mid-February and all funds are in hand by April 1.

Pastor Liz McClintock is transferred by the Annual Conference to Harwich, MA


The Rev. Walter Wnek is appointed by the Conference as our new pastor effective July 1, 2001.



APPENDIX H – FEARING TAVERN MUSEUM PHOTOGRAPHS




2013-05-30 09.47.0...




2013-05-30 09.58.4...



2013-05-30 09.58.4...



2013-05-30 09.58.5...




2013-05-30 09.58.5...




2013-05-30 09.59.0...




2013-05-30 09.59.0...



2013-05-30 09.59.0...



2013-05-30 09.59.1...




2013-05-30 09.59.2...




2013-05-30 09.59.3...



2013-05-30 09.59.4...




2013-05-30 09.59.5...



2013-05-30 10.00.0...




2013-05-30 10.00.0...



2013-05-30 10.00.0...




2013-05-30 10.00.1...



2013-05-30 10.00.1...




2013-05-30 10.00.2...



2013-05-30 10.00.3...



2013-05-30 10.01.1...



2013-05-30 10.02.0...



5-30-13 078.jpg



5-30-13 079.jpg



5-30-13 080.jpg



5-30-13 081.jpg



5-30-13 082.jpg



5-30-13 083.jpg



5-30-13 084.jpg



5-30-13 085.jpg



5-30-13 086.jpg



5-30-13 087.jpg



5-30-13 088.jpg



5-30-13 089.jpg



5-30-13 090.jpg



5-30-13 091.jpg



5-30-13 092.jpg



5-30-13 093.jpg



5-30-13 094.jpg



5-30-13 095.jpg




5-30-13 096.jpg




5-30-13 097.jpg



5-30-13 098.jpg



5-30-13 099.jpg



5-30-13 100.jpg



5-30-13 101.jpg



5-30-13 102.jpg



5-30-13 103.jpg



5-30-13 104.jpg



5-30-13 105.jpg



5-30-13 106.jpg



5-30-13 107.jpg



5-30-13 108.jpg



5-30-13 109.jpg



5-30-13 110.jpg



5-30-13 111.jpg



5-30-13 112.jpg




5-30-13 113.jpg



5-30-13 114.jpg



5-30-13 115.jpg



5-30-13 116.jpg



5-30-13 117.jpg



5-30-13 118.jpg



5-30-13 121.jpg



5-30-13 122.jpg



5-30-13 123.jpg



5-30-13 124.jpg



2013-06-17 11.05.3...



2013-06-17 11.06.0...



2013-06-17 11.06.0...



2013-06-17 11.06.1...



2013-06-17 11.06.4...



2013-06-17 11.06.5...



2013-06-17 11.07.0...



2013-06-17 11.07.1...



2013-06-17 11.07.2...



2013-06-17 11.08.3...



2013-06-17 11.09.0...



2013-06-17 11.09.1...



2013-06-17 11.09.2...



2013-06-17 11.10.1...



2013-06-17 11.10.24...



2013-06-17 11.10.24...



2013-06-17 11.10.5...



2013-06-17 11.11.2...



2013-06-17 11.11.4...



2013-06-17 11.12.0...



2013-06-17 11.14.3...



2013-06-17 11.14.3...



2013-06-17 11.15.1...




2013-06-17 11.15.2...



2013-06-17 11.15.2...



2013-06-17 11.15.2...



2013-06-17 11.15.4...



2013-06-17 11.16.5...



2013-06-17 11.17.0...



2013-06-17 11.17.1...



2013-06-17 11.17.1...



2013-06-17 11.17.2...




2013-06-17 11.17.3...



2013-06-17 11.17.5...



2013-06-17 11.18.0...



2013-06-17 11.18.3...



2013-06-17 11.18.5...



2013-06-17 11.19.0...



2013-06-17 11.19.0...




2013-06-17 11.19.2...




2013-06-17 11.19.3...



2013-06-17 11.19.5...



2013-06-17 11.20.0...



2013-06-17 11.20.3...



2013-06-17 11.20.4...



2013-06-17 11.20.4...



2013-06-17 11.21.0...



2013-06-17 11.21.0...



2013-06-17 11.21.1...



2013-06-17 11.21.3...



2013-06-17 11.21.3...



2013-08-29 10.30.3...



2013-08-29 10.30.3...



2013-08-29 10.30.4...



2013-08-29 10.30.5...



2013-08-29 10.30.5...




2013-08-29 10.30.5...



2013-08-29 10.31.1...



2013-08-29 10.31.2...




2013-08-29 10.31.3...



2013-08-29 10.32.1...



2013-08-29 10.32.5...



2013-08-29 10.33.0...



2013-08-29 10.33.0...



2013-08-29 10.33.1...



2013-08-29 10.33.2...



2013-08-29 10.33.2...



2013-08-29 10.33.4...



2013-08-29 10.33.4...



2013-08-29 10.34.0...



2013-08-29 10.34.2...



2013-08-29 10.36.0...



2013-08-29 10.36.0...



2013-08-29 10.36.4...



2013-08-29 10.37.0...



2013-08-29 10.37.2...



2013-08-29 10.37.5...




2013-08-29 10.38.0...



2013-08-29 10.38.1...



2013-08-29 10.38.2...



2013-08-29 10.38.2...



2013-08-29 10.38.4...



2013-08-29 10.39.0...



2013-08-29 10.39.1...



2013-08-29 10.39.3...



2013-08-29 10.39.4...



2013-08-29 10.40.0...



2013-08-29 10.40.2...




2013-08-29 10.40.4...




2013-08-29 10.41.0...



2013-08-29 10.41.2...



2013-08-29 10.41.3...



2013-08-29 10.41.5...



2013-08-29 10.42.0...



2013-08-29 10.42.3...



2013-08-29 10.42.5...



2013-08-29 10.43.1...



2013-08-29 10.43.1...




2013-08-29 10.43.2...




2013-08-29 10.43.5...



2013-08-29 10.44.0...



2013-08-29 10.44.1...



2013-08-29 10.44.3...



2013-08-29 10.44.5...



2013-08-29 10.45.1...




2013-08-29 10.45.2...



2013-08-29 10.45.3...




2013-08-29 10.45.5...




2013-08-29 10.46.0...




2013-08-29 10.46.4...



2013-08-29 10.46.5...



2013-08-29 10.47.0...



2013-08-29 10.47.0...



2013-08-29 10.47.4...



2013-08-29 10.47.5...




2013-08-29 10.47.5...



2013-08-29 10.47.5...




2013-08-29 10.48.0...



2013-08-29 10.48.1...



2013-08-29 10.48.2...



2013-08-29 10.48.2...



2013-08-29 10.48.2...



2013-08-29 10.48.3...




2013-08-29 10.48.3...



2013-08-29 10.49.4...



2013-08-29 10.49.4...



2013-08-29 10.51.1...



2013-08-29 10.51.2...




2013-08-29 10.51.2...




2013-08-29 10.51.5...



2013-08-29 10.51.5...



2013-08-29 10.54.3...



2013-08-29 10.54.3...



2013-08-29 10.56.1...



2013-08-29 10.56.1...



2013-09-04 12.11.2...



2013-09-04 12.12.2...




2013-09-04 12.12.3...



2013-09-04 12.15.0...



2013-09-04 12.15.1...




2013-09-04 12.15.1...




2013-09-04 12.16.0...




2013-09-04 12.16.2...



2013-09-04 12.17.1...



2013-09-04 12.17.5...



2013-09-04 12.18.0...



2013-09-04 12.22.3...



2013-09-04 12.22.4...



2013-09-04 12.22.5...



2013-09-04 12.24.4...




2013-09-04 12.25.1...



APPENDIX I – FEARING TAVERN MUSEUM - MISCELLANEOUS ARTICLES & IMAGES

The Fearing Tavern



The Fearing Tavern Museum is located in Wareham, MA. In 1690 the original house was built by Isaac Bumpus, the miller. In this house, Wareham men met to vote on Wareham's incorporation in 1739. There are many artifacts to see and experience in the seventeenth century rooms. There are a granny cradle, a hearth, a horse's mudshoe, a peel, powder horns, a bellows, and antique furniture. There are iron pots, spinning wheels, a linsey-woolsey blanket, a beehive oven, a trundle bed, and a cat hole leading to the basement, a knitty-knotty, and a burl bowl. In this section of the museum, you can see Wareham's first post office, and part of a secret closet.

In 1765, Benjamin Fearing, whose family had purchased the house, had an addition built onto two sides of the building. The Fearing addition has six rooms, including a taproom. When you walk in the

front door, to your right is the Fearing East Parlor, and to your left is the Fearing West Parlor. These rooms contain period furnishings, such as a grandfather clock with wooden gears, a piano with a mirror under it so the ladies could be sure their ankles were not showing, china that is fragile and delicate, and a sampler done by a girl who lived here in Wareham. The West parlor connects to the room, which Benjamin Fearing made into a tavern to serve food and drinks to Wareham residents and visitors arriving by stagecoach. The owner had a miniature elevator, called a "dumb waiter" to transport bottles and money from downstairs to upstairs or the other way around. Upstairs there are bedrooms, a children's playroom, and part of a secret closet.

Early in the 1800's, an ell was added to the rear of the building. This part contains a kitchen and a borning room, or sick room, downstairs and two bedrooms and a parlor upstairs. This part was built as a boarding house for men who were working in the factory that was across the street. Some of the interesting items found here are a bed that is shaped like a sleigh, another bed with hand-carved wooden cannon balls, a rolling wheel invented to measure land, and an antique music box.

The Fearing Tavern Museum was restored by the Wareham Historical Society. It is dedicated to Irene and Raymond Rider, who made sure it didn't go to waste. Come and see this house because it's been here for centuries!

by Fabian D. and Meghan C.

The Fearing Tavern Museum

Open July and August

FORM B - BUILDING

Assessor's number

USGS Quad

Area(s)

Form Number


132-1001

Wareham

B

WRH.2

Massachusetts Historical Commission
Massachusetts Archives Facility
220 Morrissey Boulevard
Boston, Massachusetts 02125



Sketch Map

see attached map

Town Wareham

Place (*neighborhood or village*) _____

Wareham

Address 8 Elm Street

Historic Name Fearing Tavern

Uses: Present education

Original social

Date of Construction c. 1690

Source _____

Style/Form Federal

Architect/Builder _____

Exterior Material:

Foundation stone

Wall/Trim wood frame

Roof asphalt shingles

Outbuildings/Secondary Structures _____

Major Alterations (*with dates*) _____

modern replacement door, wood surround

Condition good

Moved X no _____ yes Date _____

Acreage 0.15

Setting highway

Recorded by J.E. Klee, J.D. Emidy and I. Matos

Organization PAL

Date (*month/day/year*) March 2005

BUILDING FORM

ARCHITECTURAL DESCRIPTION ☒ *see continuation sheet*

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings within the community.

HISTORICAL NARRATIVE ☒ *see continuation sheet*

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES ☒ *see continuation sheet*

☒ **Recommended for listing in the National Register of Historic Places.** *If checked, you must attach a completed National Register Criteria Statement form.*

INVENTORY FORM CONTINUATION SHEET

Community:
Wareham

Property Address:
8 Elm Street

Massachusetts Historical Commission
Massachusetts Archives Facility
220 Morrissey Boulevard
Boston, Massachusetts 02125

Area(s)

Form No.

ARCHITECTURAL DESCRIPTION

The Fearing Tavern is located at 8 Elm Street, in Wareham. It is a two-story, Federal-style building with a side gable roof and a T-shaped plan made up of the main block and an addition from the center of the north elevation. The roof is pierced by two brick chimneys toward the ends of the ridge, and is clad with asphalt shingles. The exterior walls are covered with wood clapboards, and the foundation is constructed of stone. The main entrance is centered on the south elevation and consists of a wood panel door flanked by multi-pane sidelights over wood panels, and with flat pilasters supporting a broken pediment. Fenestration consists of twelve-over-twelve, double-hung sash windows with simple wood surrounds. The building is in excellent condition. Alterations to its original appearance include the modern replacement door and wood surround.

HISTORICAL SIGNIFICANCE

The original building at the Fearing Tavern was constructed about 1690 by Isaac Bump (or Bumpus) (1642-?), the town miller, who had a grist mill nearby. The building was set across the road from what would become the location of the Wareham Town Green and the meetinghouse (1735), at the center of the town. This area was known as Fresh Meadow Village in the time of the construction of Bumpus' building, and was a part of Rochester. It remained so until Wareham was incorporated in 1739. Fresh Meadow Village consisted of all of the lands on the west side of the Wankinco River, including the later villages of Tremont (or West Wareham), South Wareham, and Centre and Narrows villages (Rider 1977: 21,62,63).

Bump's property is said to have included 26½ acres, bounded on the east by the Wankinco River, upon which his mill was constructed. In 1747, Bump sold the house and property to Israel Fearing (1682-1754), the son of Isreal and Elizabeth (Wilder). The younger Israel Fearing moved from his birthplace of Hingham to Wareham, and became the first of the family in this town. He was married to Martha Gibbs, and they had nine children. He served as a town selectman in 1744 and as a justice of the peace in 1747. Fearing retained the building essentially as Bump had constructed it—a small, two-story, four room house which was oriented to the north (Anonymous n.d.; Rider 1977:5-6,100).

Benjamin Fearing, one of five sons of Israel, inherited the house upon the death of his father (Rider 1977:119). He enlarged it by adding four rooms and raising the roof to accommodate a full attic, in the process reorienting the building so that the primary entrance was on the south elevation. A third phase of construction of the building was carried out in 1800, when a rear, two-story ell was added (Anonymous n.d.).

In the early 1800s, Benjamin Fearing's house was located along the stage coach route through town. It became a stopping point for the coach, where a meal and lodging could be had for the weary traveler, and was known simply as "Benjamin's House" (Rider 1989:110). Benjamin's son, William Fearing, became the town clerk, and established Wareham's first post office in the building in 1814. William would later become the postmaster of Wareham (Rider 1977:101).

An 1832 map of Wareham shows the building labeled simply as an inn. One other building was located on the same side of Elm Street at that time, while three buildings are shown on the south side of the same segment of the road. On the east side of the Wankinco River, the Wareham Iron Company had developed its facility. The damming of the Wankinco River for the iron company flooded a large portion of the original 26½-acre parcel. To the west, the town center was developing at this time, with the Congregational church, a school, and approximately 10 other buildings nearby (Bourne 1832). By

INVENTORY FORM CONTINUATION SHEETCommunity:
WarehamProperty Address:
8 Elm Street**Massachusetts Historical Commission
Massachusetts Archives Facility
220 Morrissey Boulevard
Boston, Massachusetts 02125**

Area(s)

Form No.

1850, a small number of other buildings had been constructed in the area, but the biggest change was the railroad line that passed by the west side of the Fearing property, between it and the Congregational church (Whitlock 1850). By 1879, the Wareham Iron Company buildings on the east side of the river had been purchased by the Parker Mills. Parker Mills had also constructed a large facility on the south side of the road, west of the river, over the outfalls of the pond. Mrs. William S. Fearing is shown as the owner of the Fearing property at this time. The parcel had been reduced by the separation of two lots at the eastern portion of the parcel, along the shore of Parker Mills Pond. West of the Fearing property, the Parker Mills Depot had been constructed, a new school was built, and the center of the village contained a store, carriage factory, the Congregational church, a Methodist church, and 15 to 20 residences. Of these, three were owned by members of the Fearing family (Walker 1879).

A 1903 map of Wareham illustrates Wareham Centre as a dense, residential and commercial area. East of the river, the Tremont Nail Company, now having expanded its holdings from Tremont to the former Parker Mills facility, had constructed more buildings on the site, and a residential area had grown up to the east of the facility. The company had also built new structures on the south side of Elm Street, west of the river. On the west side of the railroad right of way, the village center now included a park, the town office, the Methodist and Congregational churches, the school, and a number of estates. Smaller residential properties occupied a number of parcels as well, particularly along Main and High streets. The Fearing property was labeled as the W.H. Fearing estate in 1903 (Anonymous 1903).

The property remained in the Fearing family until 1958, when they gifted it to the Wareham Historical Society for preservation. The Society performed substantial renovations to the building, which had fallen into disrepair over the first half of the century. The historical society operates the Fearing Tavern as a museum with period furnishings (Anonymous n.d.).

BIBLIOGRAPHY and/or REFERENCES

- Anonymous. *Brief History of Fearing Tavern with Rough Floor Plan Attached*. On file at the Wareham Library. n.d.
Rider, Raymond A. *Life and Times in Wareham Over 200 Years 1739-1939*. Wareham Historical Society, Wareham, Massachusetts. 1989.
The Fearings and the Fearing Tavern with the Bumpus Family. Raymond A. Rider, Wareham, Massachusetts. 1977.

Maps

- Anonymous. *Town of Wareham Plymouth County*. On file at Wareham Free Library, Wareham, Massachusetts. 1903.
Bourne, Sylvanus. *Map of Wareham*. On file at Wareham Free Library, Wareham, Massachusetts. 1832.
Thacher, Rowland, Israel Fearing and Joshua Gibbs. *Map of the Town of Wareham*. On file at Wareham Free Library, Wareham, Massachusetts. 1795.
Walker, George H. *Atlas of Plymouth County, Town of Wareham and Marion Massachusetts*. 1879.
Whitlock, _____. Wareham Plymouth County Mass. On file at Wareham Free Library, Wareham, Massachusetts. 1850.

INVENTORY FORM CONTINUATION SHEET

Massachusetts Historical Commission
Massachusetts Archives Facility
220 Morrissey Boulevard
Boston, Massachusetts 02125

Community:
Wareham

Property Address:
8 Elm Street

Area(s)

Form No.

National Register of Historic Places Criteria Statement Form

Check all that apply:

- ☒ Individually eligible ☐ Eligible **only** in a historic district
☐ Contributing to a potential historic district ☐ Potential historic district

Criteria: ☒ A ☐ B ☒ C ☐ D

Criteria Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Statement of Significance by Jeffrey D. Emidy

The criteria that are checked in the above sections must be justified here.

The Fearing Tavern is significant under NRHP criteria A and C at the local level. Under criterion A, the building is significant because of its role as an inn, tavern, and meeting place since the eighteenth century. It has hosted town proprietors' meetings, visiting travelers, and likely most types of social functions that occurred within the town in the eighteenth and nineteenth centuries. Under criterion C, the building is eligible for the NRHP as a rare, surviving local example of colonial architecture. It possesses integrity through its retention of original materials, massing, and interior spaces. The building is in an excellent state of preservation.

INVENTORY FORM CONTINUATION SHEET

Community:
Wareham


Property Address:
8 Elm Street

**Massachusetts Historical Commission
Massachusetts Archives Facility
220 Morrissey Boulevard
Boston, Massachusetts 02125**

Area(s)

Form No.

SITE MAP



road over the dam, called Stage Coach Road, went to Sandwich.

As the industrial revolution was getting underway, large sums of money were provided to improve and provide new roads and bridges all over town. The town records note that the "Wareham Manufacturing Co. paid \$20.36 for cutting stone and repairing road."

The Stage Coach and Early Wareham

In the early 1800's the Stage Coach came into Wareham, when the roads were narrow and difficult ways for even the crudest vehicles. The coach was slow and cumbersome and needed several places to stop on its rough journey from town to town. Along its route many ordinaries sprang up to serve the needs of the passengers and the tired horses pulling this awkward vehicle over deeply rutted roads. Among the stops was the Fearing Tavern, known then as "Benjamin's House," where food and lodging could be obtained by the weary traveler. There was also a great barn in the rear where fresh horses were kept to replace the tired, hard-working coach horses.

These public houses were regularly patronized and most were highly successful until the railroad came in 1846. Then they were the first to suffer a loss of patronage when the Stage Coach was abandoned. With the closing of these roadside accommodations went the sales of liquor and food and the jobs of the innkeeper and his helpers. Not all of the ordinaries ceased operation, as some were within the town and near the mills, where they continued to do business for many years.

The Stage Coach from Wareham to New Bedford took three hours, with maximum discomfort and limited accompanying baggage. The route was the Country Road to Rochester across the narrow part of the Weweantic River, over the dam of a grist mill or sawmill going by Mary's Pond and Blackmore's Pond, heading towards Mattapoisett. This route avoided the great marshes along the Weweantic and crossed the bridge in Rochester over the Sipican River dam and finally reached New Bedford.

Another section of the Stage Coach route was a deeply rutted road to Sandwich, which at the time contained the area we know as Bourne and Buzzards Bay. The boundary ran through Cohasset Narrow, up Red Brook to a point at White Island Pond. More particularly, "at Red Brook head of Buzzards Bay a stone monument.....near Dutchmen's Bridge or Dutchmen's Ditch Bridge, a stone monument.....on the southerly side of White Island Pond, a stone monument..." (Town Records)

The road I
not meet Red I
at least a half a
map made by S
1800's shows I
"Dutchmen's I

The Country

In *Colonic*
the author de
stopped at Tre
take a wagon t
threading its w
other sandy ro
ly, this windin
Hill where Joh

Bliss turn
shade over th
Purple wood :
fields with yel

The silenc
ing views of ti
careful look de
dust as the an
the ruts of th
sand, leaving
rotate behind
an older man

The road
lage comes on
butcher with
or Agawam, :
wares. Occasi
pills at his feet
hurry him on
doctor's prese

There is a
stone in the r
the reins on th
road cracks in

Woods su
roadway, con
fle the sound:
Root Bliss)

funds for the poor would raise the taxes of the affluent.

Herring

The Wankinco River's headwaters were cold springs, not inviting to the herring. The Weweantic River's headwaters were several ponds in Middleboro, and were a magnet to the fish.

"The Town met att the Day and time set att the adjurdment. The Moderator put to vote whether the town was for haveing 410 Barel of hering catchet out of ye several Streams in Wareham ye Present year for Markit Provide the men that catchet them would Pay to ye town four shillings Bounty on each Barel for ye youse of the town and ye vote Past in the Affirmative:

oute of Weweantic River	300 barrels
oute of Agawam River	80 barrels
oute of Wankinco River	8 barrels
oute of Cohasit Creek socaled Cohasset Narrows . .	16 barrels
oute of ye Brook by Micah Gibbs (Red Brook)	6 barrels
	410 barrels"

Later in town history, the sale of rights to catch herring was auctioned off at the Fearing Tavern, leaving the successful bidder the obligation to sell four hundred alewives to any householder for 64 cents, and to give all widows a full barrel of herring.

Alewives (herring) were always a source of food and profit. They came early into regulation and there was a persistent effort to make sure Wareham got its part of the shared rivers.

There was a problem in sharing the catch of fish from the Weweantic and ensuring a "passage up and down the river for ye fish." Agawam River was shared with Plymouth in an agreement which was mutually changed from time to time to the advantage of first one town and then the other. Red Brook, a boundary stream with Sandwich, seemed almost free of dispute.

The Weweantic and Agawam Rivers became sources of power for many mills, and dams were built to hold a pond of water for year-round operation of the industries. It was voted by the town each year to see that a sufficient passageway was provided around these dams, and each river had its own committee to watch for obstructions.

Also, a great deal of poaching went on in the towns, for the herring came in great numbers. The poor people and others were tempted to take large amounts for their needs.

At first, great efforts were made to prevent the illegal catching

of fish thro
minimum c
poaching,
themselves
run, and we
tee, the con

In 1745
Briggs to t
Wareham r
money in it
money to fu
convert the

At a tow
to the highe
alewives thi
fish." The t

The Fe
these rivers
and down t
care for the

"And J
Great Court
River." This

After th
the first tin
Gibbs, Jess
Fish."


It was v
(The town u
that "no oy
leave of Joh
penalty of p

Later, t
get an act
General Co
Revolutiona

Herring
Because the
was exclud
ing places v
town, and p


The las
meeting. Th
ty to appoin

V. 12



REMEMBERING WHEN

Wareham's
Fearing
Tavern,
as seen
in July
1979.



Standard-Times library photo



A look back at the Fearing fam

By RAYMOND A. RIDER


WAREHAM— Israel Fearing had a home in Agawam now called East Wareham that burned in the mid-1930s. In its place is a flat-roofed house built by Joshua Hall, son of Daniel Hall who owned the Wareham Courier. "Josh" and his wife, Edith, lived in this house until they died.

In the original Fearing Homestead of Israel lived John, one of his sons who became the squire after his father died in 1757. John then married and built a house on the Country Road going from Wareham to Rochester Center. Like all roads that have lost their original standing, its name has changed. This happens especially if the road is interrupted by a bridge, another more important road, or a railroad — all of which happened to the Country Road as Route 6 came down Old Main Street.

Because John Fearing lived on the hillside, the road was named Fearing Hill Road. Incidentally, the road went to County Road; on the other side, Country Road came to be known as Mary's Pond Road in Rochester.

John Fearing, as we said, became Squire Fearing, as Justice of the Peace in his father's place. As an officer of the court, he tried all but criminal cases, either in his home or at his brother Benjamin's House (Fearing Tavern). He was not a lawyer, but he learned from the lawyers who practiced before him and gave him the privilege of reading their law books. This enhanced his abilities to conduct his court and aided his judgment in his decisions.

The stocks and whipping post were visible from the church and from Benjamin's House — a reminder to the patrons of the tavern and to the meeting-house attendants to be on their best behavior — or else.



Fearing Homestead

John Fearing's house was larger than his father's, but it was no mansion either. A later addition as large as the original house gave the home a rambling appearance but a poor architectural perspective. The home was last occupied by Mr. and Mrs. Walter J. Ligon, she being the last Fearing descendant to live in the homestead. The Ligans had in mind to give the old homestead to the Wareham Historical Society, but the society had purchased the old William Fearing-Benjamin Fearing Homestead that had more historical background.

This house, once owned by John Fearing, is now minus the wing, leaving the original building restored much as it used to be.

One of the descendants had a name of enormous length, it being "Aldaberontophoseofomia Bowen Fearing." She was a resident of the John Fearing House.


A picture of her is in the west parlor or "town room" of the Fearing Tavern. She is also referred to as the "Boston

Belle." She was related to William Root Bliss, author of "Colonial Times on Buzzards Bay," essentially a story of the town of Wareham in the 1700s, and the "Old Colony Town and the Ambit of Buzzards Bay," again a story of land bordering this great bay facing south. It includes Plymouth, Onset and other points in Wareham along the shores, the flight of the albatross, the story of the last man on a wreck, and seven days in a jinrikisha (rickshaw). The author married Elizabeth Fearing, one of the great-great-granddaughters of Israel Fearing of the Agawam Plantation who was a grandson of John Fearing of Norfolk County in Old England, landing in Hingham in 1635.

Israel Fearing who came to Agawam in 1720 was formerly of Hingham. He is the man given great credit for the incorporation of Wareham, composed of a



Northeast Parlor Fearing



Southwest Parlor Fearing

slice of Old Rochester and a called chunk of land from Plymouth call F

Discussion on rail safety to be public meeting

WAREHAM— State transportation officials will address the need for safety improvements at Cape rail crossings at a public meeting ex-

pected to take place in a month or so. Gov. Michael Dukakis has agreed to send Executive Office of Transportation and Construction (EOTC) officials to hear the concerns of area residents upset by the lack of safety features at

for the ing, s of re pass Th is de will



Clearance Sale

Lee Men's

Jeans & Cards

Correction



Isaac Bump's house, sold to Israel Fearing in 1747, was expanded and transformed into a tavern by Israel's son Benjamin. Preserved by the Wareham Historical Society as the Fearing Tavern Museum, it is open on summer weekends.

West End of town. The area containing his farm would be known as Fearing Hill and that part of the Old Country Road would be known as Fearing Hill Road.

He received the honor his father once enjoyed, the office of justice of the peace. There were others in the community who had been elevated to this position, but John succeeded to his father Israel's special place as the leading justice.

Having inherited his ancestor's mantle in 1755 (he received his appointment in Middleboro on June 26), Squire John Fearing accepted all of the responsibilities of conducting court, both at his home on Fearing Hill and also at Benjamin's Inn (Fearing Tavern, or Benjamin's House). Here the stocks and whipping post were erected in the yard on the west side of the tavern for the convenience of the justice and the constabulary. Sentences could be carried out quickly with little trouble and no loss of time.

The culprits would pay penance of the allotted time set by the presiding Squire Fearing. Sometimes a fine of several shillings would be assessed instead for their civil errors.

Only the most minor misdemeanor could be handled by the local court, such as swearing, insults or minor assaults, debts of one kind or another, thievery and failure to attend church.

The power of John Fearing, Esquire, went beyond the restraint of the local people in matters of law. He also governed the domestic as well as the civic life of the citizens of the Town of Wareham. He was often called upon to perform marriages after intentions were filed with the town clerk and announced three times in town meetings. His position was maintained, not because he was learned in the laws, but because he was one of the "most sufficient persons" dwelling in the country, known to be loyal and dignified and possessed of lands or tenements yielding certain annual increments.

Benjamin Fearing

Israel Fearing gave his son Benjamin primarily the lands he had purchased from Isaac Bumpus. There were some 28 acres — much of it flooded for water power. This parcel extended west to what is now Route 195 and north to Tihonet, east to the Fresh Meadows and south to John Bumpus' lot.

In bequeathing this property to Benjamin, it would seem that Israel made a wise choice, as Benjamin became a successful businessman. He was part of the industrial revolution in Wareham and profited greatly from it. Of all the children of Israel, Benjamin, though not the firstborn son, received the most profitable part of his father's estate.

In 1754, Benjamin took the former dwelling house of Isaac Bumpus and turned it into a public house, known variously as "a house of entertainment," a "grog shop," a tavern or an inn. It was fondly known locally as "Benjamin's House" and is now the Fearing Tavern on Elm Street.

Benjamin's Inn was centrally located near the meetinghouse. It was a popular place to gather for the news; sometimes to listen to John Fearing, justice of the peace, holding court there; or to gaze at a man in the stocks or one tied to the whipping post. His place was also a shelter for the freezing congregation from the meetinghouse on Sundays. The house was heated by a huge fire place, but the meetinghouse was not heated at all.

Success seemed assured, because in 1765 Benjamin enlarged the property by building four new rooms and expanding the lean-to to encompass a tap room and bar. Once he had a bar set up and began to serve liquor, the town meeting would adjourn there to sell the poor people, especially during the winter months. It was warmer there, and besides, liquor was available to lubricate the proceedings of the meeting. (The selling of the poor was an auction of those unfortunate people who had no means of sup-

Fearing Tavern

62

Life and Times in Wareham

Over 200 years 1739 - 1935

"Seeing my performance among you have found such acceptance that you have given me a call to minister to you, officially in holy things, and having seriously weighed the matter and asked the direction of heaven, I conclude your call to be from God. Therefore being deeply sensible of my own unworthiness and unfitness for the great work, yet depending on Christ, do accept your call depending on you for such support from time to time as the Gospel does require; earnestly asking your prayers to God for me, that when I have preached to you, I myself may not be found cast away, but when I am called to give an account of my ministry to God the Great Shepherd and Bishop of Souls, I may do it with joy, having many of your souls as seals of my ministry and Crown of rejoicing.

Wareham, Oct. 17, 1739

signed, Rowland Thacher"

He was unanimously approved by Selectmen Jireh Swift, Jeremiah Bumpus and Town Clerk Jonathan Hunter.

The day before the ordination of Rowland Thacher, the following persons incorporated into a church:

Mary Besse; Sarah Blackmer; William Blackmer, Deacon; Abigail Bump; Edward Bump (died Nov. 24, 1745); Hannah Bump; Jane Bump; Jonathan Bump; John Bump; John Bump, Jr.; Isaac Bump (died 1761); Martha Bump; Mary Bump; Rebecca Bump; Samuel Bump (died May 26, 1770); Susannah Bump; Mercy Burgess; Elizabeth Doty; Hannah Doty; Rebecca Edwards; John Ellis, Deacon; Rose Ellis; Joshua Gibbs, Deacon; Mercy Gibbs; Ebenezer Hamlin, Deacon; Ruth Hamlin; Thomas Hamlin; Hopestill Hunter; Deborah Landers; Ebenezer Luce; Sarah Luce; Mary Ellis May; John Norris; Mary Norris; Ann Sanders; Henry Sanders; Thankful Sanders; Deborah Savery; Sarah White; Rowland Thacher, Pastor.

In 1739, when Rowland Thacher was ordained, Edward Bump was chosen to be master of ceremonies. Thacher proceeded to carry out his duties, "Not according to the custom of tavern selling of victuals, but as shall be judged reasonable by the people." The next day he organized his church.

Next, he set about building a house, probably in 1739. Built on land owned by Isaac "Bump the Miller," it was part of the Rochester Sea Lot on the bank of the Wankinco River. The original house had four rooms downstairs and four rooms on the second floor, with stairs leading to a large open attic. There were five fireplaces and a huge center chimney. When first con-

ructed, the house faced north and the foundation was granite blocks.

It sat on land later taken by the railroad for its tracks which ultimately extended to Provincetown. The fireplaces and chimney were removed to lessen the weight when the house was moved off the railroad right of way, turned around to face south, and set on a foundation on the north side of the road "going to Middleboro and Carver," now Route 28.

Attending an unheated church in that time was an endurance contest. It was the reverend's practice to mount the pulpit stairs and, once inside, sit down in order to be invisible to all below him. He would arise to start with a prayer; then the deacon would lead the singing in a voice hoarse from calling to his oxen the day before, but he bravely rasped out the psalm.

When that was over, the deacon would turn the hour-glass for the parson to start his sermon. Sometimes it was necessary to turn the hour-glass two or three times as the clergyman proceeded from "thusly" to "thirdly" up to "twelfthly." Then he would open up a new gradient to cover the rest of the world and God's country.

Toward the end, he would come to "finally", which could include several "finals." When "Amen" was sounded to end the sermon, the boys flew for the doors as the deacons jumped nimbly aside to prevent themselves from being bowled over.

Lunches were then eaten and business transacted among the men. After 1757, when Benjamin's House was open, they sat at the tables talking and enjoying a mug of grog. Church resumed in the afternoon for an hour or more before the start for home began.

Benjamin's Inn, better known as Benjamin's House, was a mecca for the freezing congregation from the meetinghouse on Sundays. It would be over one hundred years before the town relented and put in a furnace to heat the town house/church.

Subsequently, the church membership under Rowland Thacher included:

BENSON: Ebenezer and Joannah, his wife; Joseph, Jr.; Kesiah; Samuel.

BESSE: David; Deborah; Dinah, David's wife; Jabez and Marjorie, his wife; Jabez, Jr.; Joshua; Martha, wife to Benjamin; Robert and Ruth, his wife; Ruth, wife to Jabez; Sarah, wife of Nehemiah.

BOURNE: Ebenezer.



BRIEF HISTORY OF FEARING TAVERN WITH ROUGH
FLOOR PLAN ATTACHED. ELL WHICH WAS ADDED
IN 1800 AND WHICH HAS NOT YET BEEN RESTORED
IS NOT OPEN TO VISITORS. IT IS NOT DESCRIBED
AND IS NOT SHOWN ON THE DRAWING.

WH
974.486
B.I

The Fearing Tavern is believed to be the oldest house in Wareham; built by Isaac Bump, or Bumpus, the town miller, who owned a grist mill nearby.

Israel Fearing bought the property from Bumpus in 1747 and it remained in the Fearing family until 1958 when the Wareham Historical Society acquired it by gift from the Fearings to restore and preserve as one of the distinguished and important landmarks of the area.

This old two-storey house was built in three distinct periods. The original structure, built in 1690, and which then faced north, consists of two lower rooms, two upper rooms, two chimneys each with a fireplace and oven, a lean-to and cellar. The lean-to is now part of the taproom. When the floor of the kitchen which the Society calls the Publick Room was restored, the original cellar was found. Access to it was probably by way of a trap door.

The small room next to the Publick Room with a window facing east was later used as the town post office (the first) from about 1765-1800.

In 1765 (the date is imprinted in the original plaster of the front hall) Benjamin Fearing, son of Israel, added four rooms to the by then seventy-five year old building. This second portion has four large rooms with a stairway and halls and a front door facing south. He also added to the lean-to and put a fireplace in what was to become the taproom. The beam separating the old lean-to from the addition can be very plainly seen. The bar which had been removed from the taproom at some later time was found intact and carefully restored and placed in its original position. The original archway over the bar had never been disturbed.

Finally Benjamin raised a roof over the entire structure making room for a large attic in which are the original hand-hewn beams, forty feet or more in length, each numbered and notched. Three exceptionally well-built flights of stairs rise from the attic floor to skylights in the roof. Some believe that the stairs were built to provide access to the roof in case of fire while others have suggested that small cannon may have been hauled up over them and aimed from the roof. There is an iron hook in the roof to support this latter theory.

The third section, built in 1800, consists of an ell at the rear facing north with its two storeys, fireplaces and ovens. This part of the house has not yet been restored and is not open to visitors.

It will be noted that the ceilings in the 1765 section are higher than those in the original structure which accounts for the different floor levels.

The Tavern was the scene of early activities in the Town of Wareham. Israel Fearing was the first Justice of Peace commissioned in Agawam Purchase by George I. He had authority to perform marriage ceremonies, settle accounts, receive complaints, settle disputes, hold trials, record legal documents and make indentures and agreements. The selectmen of the town held their meetings in the taproom and were served victuals and grog at town expense. Fearing tradition tells of a British soldier who lay hidden for three days from Liberty Men in the closet reached by a secret passage opening off the second-floor southeast chamber of the 1765 addition. The Captain of Town Militia maintained his headquarters in the Tavern and there was always a free lunch when a new minister was installed. Because of the situation of his dwelling before the days of stagecoaches it seems probable that Isaac Bump, along with operating his grist mill, entertained travelers when the horse, the river and "Shank's Mare" were the chief modes of transportation.



W.F.
0-1, 4-6
FEB

Patrons

MR. and MRS. M. B. MAKEPEACE, Wareham
GEORGE R. FRENCH, Onset
FLORA B. MCGREGOR, Onset
MRS. CHARLES H. MEYER, Onset
DR. and MRS. ROBERT N. LaMARCHE,
Springfield
FIRST SPIRITUALIST CHURCH, Onset
DOROTHY B. MARSH, Onset
WAREHAM BOARD OF SELECTMEN

MARILYN E. KEITH, Pocasset
DECAS CRANBERRY CO., INC., Wareham
MILDRED J. BRADSHAW, Onset
ALEX PULANSKI, Onset
RAYMOND FITZGERALD, Onset
FRANK MESSINA, Melrose
PAUL LINDSEY, Onset
DR. and MRS. SAMUEL GOLDFARB, Onset
MR. and MRS. LOUIS O. ST. AUBIN, Achushnet

The FEARING TAVERN MUSEUM

ELM STREET WAREHAM, MASS.

The Fearing Tavern is believed to be the oldest house in Wareham; lived in by Isaac Bump, or Bumpus, the town miller, who owned a grist mill nearby.

Israel Fearing bought the property from Bumpus in 1747 and it remained in the Fearing family until 1942. The Wareham Historical Society acquired it by gift from Mr. and Mrs. Ernest Blanchard to restore and preserve as one of the distinguished and important landmarks of the area.

This old two-storey house was built in three distinct periods. The original structure, built in 1690, and which then faced north, consists of two lower rooms, two upper rooms, two chimneys each with a fireplace and oven, a lean-to and cellar. The lean-to is now part of the taproom. When the floor of the kitchen which the Society calls the Publick Room was restored, the original cellar was found. Access to it was probably by way of a trap door.

One of the most unusual features of the old building is that all of its ancient fabric is original and intact.

The small room next to the Publick Room with a window facing east was later used as the town post office (the first) from about 1765-1800.

In 1765 (the date is imprinted in the original plaster of the front hall) Benjamin Fearing, son of Israel, added four rooms to the by then seventy-five year old building. This second portion has four large rooms with a stairway and halls and a front door facing south. He also added to the lean-to and put a fireplace in what was to become the taproom. The beam separating the old lean-to from the addition can be very plainly seen. The bar which had been removed from the taproom at some later time was found intact and carefully restored and placed in its original position. The original archway over the bar had never been disturbed.

Finally Benjamin raised a roof over the entire structure making room for a large attic in which are the original hand-hewn beams, forty feet or more in length, each numbered and notched. Three exceptionally well-built flights of stairs rise from the attic floor to skylights in the roof. Some believe that the stairs were built to provide access to the roof in case of fire while others have suggested that small cannon may have been hauled up over them and aimed from the roof. There is an iron hook in the roof to support this latter theory.


The third section, built in 1800, consists of an ell at the rear facing north with its two storeys, fireplaces and ovens. This part of the house has not yet been restored and is not open to visitors.

It will be noted that the ceilings in the 1765 section are higher than those in the original structure which accounts for the different floor levels.

The Tavern was the scene of early activities in the Town of Wareham. Israel Fearing was the first Justice of Peace commissioned in Agawam Purchase by George I. He had authority to perform marriage ceremonies, settle accounts, receive complaints, settle disputes, hold trials, record legal documents and make indentures and agreements. The selectmen of the town held their meetings in the taproom and were served victuals and grog at town expense. Fearing tradition tells of a British soldier who lay hidden for three days from Liberty Men in the closet reached by a secret passage opening off the second-floor southeast chamber of the 1765 addition. The Captain of Town Militia maintained his headquarters in the Tavern and there was always a free lunch when a new minister was installed. Because of the situation of his dwelling before the days of stage-coaches it seems probable that Isaac Bump, along with operating his grist mill, entertained travelers when the horse, the river and "Shank's Mare" were the chief modes of transportation.



Olive Caires, Gladys Evenson and Eda Cowing, left to right, take time for a cup of tea while visiting the Fearing Tavern.



Gladys Evenson, left, and Olive Caires admire an early American doll and suspended cradle now a part of the Fearing Tavern Museum.

Doris Ward photos



3 3678 00049 5022

W.F.
974.462
V.101A

The women of the Tavern

WAREHAM — Local residents, dressed in hand-fashioned, authentic early American costumes, enjoy a bit of nostalgia by visiting the Fearing Tavern Museum in Wareham.

One of the town's most prized historical buildings, the Fearing Tavern was once the site for public meetings held by local notables, complete with "free grog," so the story goes.

The original building dates from 1690, and was built by Capt. Daniel Fearing, with additions to the structure being made in 1750 and 1765. Used for a tavern for generations, it was also the site of Wareham's first post office.

Owned now by the Wareham Historical Society, this remnant of the town's past remains closed most of the time, but is open during the summer for several hours each week.

It is also opened for special events, such as tours, Bicentennial celebrations, flower shows, and by special request of various local organizations for meetings and other activities.




In the spirit of the original Fearing Tavern atmosphere, a smile and a song by M.C. Richard Reed, left, and Eda Cowing.




A pensive moment for Eda Cowing as she admires the wheel straight from the early Fearing Tavern days.

ROUGH PLAN OF THE FEARING TAVERN



SECOND FLOOR



GROUND FLOOR

FRONT DOOR.

- ORIGINAL HOUSE (1690)
- ADDITION (1765)

Fearing Tavern is said to be the oldest existing structure in Wareham. It is a clapboard building comprised of 3 separate sections, which were each built in a different era. The oldest part of the structure was built by Isaac Bump, the miller, in 1690 on a 26½ acre parcel of land. This parcel has been reduced over the years by flooding for a holding pond, a dam, a road and sale of part of the land to the Tremont Nail Co.. The lot is now only about 2500 square feet in size. Isaac Bump operated a grist mill on the nearby mill pond. He also operated two other mills in town. He was an ancestor of Mercy Lavinia Warren Bump, better known as Mrs. Tom Thumb. On April 7, 1747 Isaac Bump sold his house and land to Israel Fearing. Israel Fearing died in 1754, leaving his son Benjamin to inherit the house, lands, and water-rights. From this time it remained in the Fearing family until 1942.

Shortly after Benjamin inherited he converted the dwelling into a tavern. Eleven years later he added four large rooms, a stairway and halls to the original structure which had consisted of two upper and two lower rooms, two chimneys, a lean-to and a cellar. He roofed the entire structure over, making a large attic with skylights and an imposing front door facing south. Originally the house had faced north. It was customary in those days upon licensing an inn, to require that it be established near a church. In this case the old Congregational Church on the green is quite visible up the road. The last section, consisting of a 2 story ell at the rear and facing north was added in 1800. The inn was a resting place for weary travelers on horseback. It became a stage coach stop only after roads widened and improved, just prior to the railroad era.

Benjamin's brother, Squire John, often used the Tavern as the place from which he dispensed justice and performed his other functions as Justice of the Peace. He could perform marriages, make indentures and agreements, settle accounts, listen to complaints and settle disputes, hear trials and record legal documents. Also, selectmen often met on the taproom and were served grog and victuals at town expense. The Public room served as town post office from 1765 to 1800. The tavern was also the headquarters of the captain of the town militia. It was also customary to provide a free luncheon everytime a new minister accepted the leadership of the church. There is a tradition that a British soldier hid from the town militia for three days in a closet reached by a secret passage in the second floor southeast chamber of the 1765 addition which backed onto a closet of the older part of the house making passage back and forth easy and undetectable.

WAREHAM FREE LIBRARY



3 3678 00049 4884

The last Fearing to live in the house was Mary Fearing and her husband William Warr. They lost the house through foreclosure in 1942. Finally the house was sold to the Historical Society for one dollar and considerations by Mr. and Mrs. William Blanchard through the efforts of Raymond Rider. Some of the \$50,000 raised for the costs of renovation were donated by three Fearing Descendants, Doris Engel, Jean Killhour, Eleanor G. Price and their husbands. There are several plaques placed throughout the tavern commemorating other ancestors and donators. The inside of the house was renovated before the outside in order to spark local interest and support. The grill for the taproom was found intact in the attic and was restored to its original position, fitting exactly into and arched beam in the taproom. The date 1765 was found to be traced into the plaster work at the right of the south entrance. Period furniture was donated to restore authenticity. Finally, split cedar shingles replaced asphalt shingles and a new roof using hand hewn beams and joists was raised one section at a time.

The imposing structure of the old Fearing Tavern on Elm St. in Wareham had been painstakingly restored over the past twenty years by the Wareham Historical Society. It is owned by the Society and is open three days a week to the public Tuesdays, Wednesdays and Thursdays from 2:00 4:00 P.M. The Historical Society has been very generous in opening the Tavern for the edification and enjoyment of school classes. The founder of the Historical Society, Raymond A. Rider, his wife, Irene, and architect Lloyd Hendrick assiduously supervised the restoration for fifteen years. Mr. Rider has written a book entitled the Fearings and the Fearing Tavern with the Bumpus Family, which explains in detail the history of the tavern and the families associated with it and other facts of general interest related to the era in which it was built.



APPENDIX J – CAPTAIN KENDRICK HOUSE PHOTOGRAPHS



2013-05-31 09.34.5...



2013-05-31 09.35.0...



2013-05-31 09.35.1...



2013-05-31 09.35.1...



2013-05-31 09.35.3...



2013-05-31 09.35.3...



2013-05-31 09.35.5...



2013-05-31 09.36.1...



2013-05-31 09.36.2...



2013-05-31 09.36.3...



2013-05-31 09.37.1...



2013-05-31 09:37.24...



2013-05-31 09.37.24...



2013-05-31 09.37.3...



2013-05-31 09.37.4...



2013-05-31 09.38.0...



2013-05-31 09.38.0...



2013-05-31 09.38.3...



2013-05-31 09.38.4...



2013-05-31 09.38.4...



2013-05-31 09.38.5...



2013-05-31 09.39.1...



2013-05-31 09.39.2...



2013-05-31 09.39.3...




2013-05-31 09.39.5...



2013-05-31 12.39.2...



2013-05-31 12.39.2...



2013-05-31 12.39.3...



2013-05-31 12.39.3...



2013-05-31 12.39.4...




2013-05-31 12.39.4...




2013-05-31 12.39.4...



2013-05-31 12.39.5...




2013-05-31 12.40.0...



2013-05-31 12.40.0...



2013-05-31 12.40.1...



2013-05-31 12.40.1...



2013-05-31 12.40.2...



2013-05-31 12.40.4...



2013-05-31 12.40.5...



2013-05-31 12.40.5...



2013-05-31 12.41.0...



2013-05-31 12.41.1...




2013-05-31 12.41.1...



2013-05-31 12.41.2...



2013-05-31 12.41.2...




2013-05-31 12.41.3...



2013-05-31 12.41.3...




2013-05-31 12.41.4...




2013-05-31 12.41.5...



2013-05-31 12.42.0...




2013-05-31 12.42.0...



2013-05-31 12.42.1...



2013-05-31 12.42.1...



2013-05-31 12.42.2...



2013-05-31 12.42.3...



2013-05-31 12.42.4...



2013-05-31 12.42.4...



2013-05-31 12.42.5...



2013-05-31 12.42.5...



2013-05-31 12.42.5...



2013-05-31 12.43.0...



2013-05-31 12.43.0...



2013-05-31 12.43.1...



2013-05-31 12.43.1...



2013-05-31 12.43.1...



2013-05-31 12.43.2...




2013-05-31 12.43.2...



2013-05-31 12.43.3...



2013-05-31 12.43.3...




2013-05-31 12.43.3...



2013-05-31 12.43.4...



2013-05-31 12.43.4...



2013-05-31 12.43.5...



2013-05-31 12.43.5...




2013-05-31 12.43.5...



2013-05-31 12.44.0...



2013-05-31 12.44.1...



2013-05-31 12.44.1...



2013-05-31 12.44.1...



2013-05-31 12.44.2...




2013-05-31 12.44.2...




2013-05-31 12.44.3...




2013-05-31 12.44.3...




2013-05-31 12.44.3...




2013-05-31 12.44.4...



2013-05-31 12.44.4...




2013-05-31 12.44.5...



2013-05-31 12.44.5...




2013-05-31 12.45.0...




2013-05-31 12.45.0...



2013-05-31 12.45.1...



2013-05-31 12.45.1...



2013-05-31 12.45.1...



2013-05-31 12.45.1...




2013-05-31 12.45.3...




2013-05-31 12.45.3...



2013-05-31 12.45.4...




2013-05-31 12.45.4...



2013-05-31 12.45.5...



2013-05-31 12.45.5...



2013-05-31 12.46.0...



2013-05-31 12.46.1...



2013-05-31 12.46.1...



2013-05-31 12.46.2...



2013-05-31 12.46.2...




2013-05-31 12.46.3...




2013-05-31 12.46.3...



2013-05-31 12.46.3...



2013-05-31 12.46.4...




2013-05-31 12.46.4...



2013-05-31 12.46.5...




2013-05-31 12.46.5...



2013-05-31 12.47.0...




2013-05-31 12.47.1...



2013-05-31 12.47.1...




2013-05-31 12.47.2...



2013-05-31 12.47.5...



2013-05-31 12.47.5...



2013-05-31 12.48.0...



2013-05-31 12.48.0...



2013-05-31 12.48.1...



2013-05-31 12.48.1...



2013-05-31 12.48.2...



2013-05-31 12.48.3...



2013-05-31 12.48.3...



2013-05-31 12.48.5...



5-30-13 125.jpg



5-30-13 126.jpg



5-30-13 127.jpg



5-30-13 128.jpg



5-30-13 129.jpg



5-30-13 130.jpg



5-30-13 131.jpg



5-30-13 132.jpg



5-30-13 133.jpg



5-30-13 134.jpg



5-30-13 135.jpg



5-30-13 136.jpg



5-30-13 137.jpg



5-30-13 138.jpg




5-30-13 139.jpg



5-30-13 140.jpg



5-30-13 141.jpg



5-30-13 142.jpg



5-30-13 143.jpg



5-30-13 144.jpg



5-30-13 145.jpg



5-30-13 146.jpg



5-30-13 147.jpg



5-30-13 148.jpg




5-30-13 149.jpg




5-30-13 150.jpg



5-30-13 151.jpg



5-30-13 152.jpg



5-30-13 153.jpg



5-30-13 154.jpg



5-30-13 155.jpg



5-30-13 156.jpg



5-30-13 157.jpg



5-30-13 158.jpg



5-30-13 159.jpg



5-30-13 160.jpg



5-30-13 161.jpg



5-30-13 162.jpg



5-30-13 163.jpg



5-30-13 164.jpg



2013-06-17 09.00.3...



2013-06-17 09.00.4...



2013-06-17 09.01.1...




2013-06-17 09.01.2...



2013-06-17 09.01.5...



2013-06-17 09.02.0...




2013-06-17 09.02.1...



2013-06-17 09.02.3...



2013-06-17 09.02.4...




2013-06-17 09.03.1...



2013-06-17 09.03.3...



2013-06-17 09.04.0...



2013-06-17 09.06.1...




2013-06-17 09.07.4...



2013-06-17 09.08.3...



2013-06-17 09.09.1...



2013-06-17 09.10.3...



2013-06-17 09.12.5...



2013-06-17 09.12.5...



2013-06-17 09.13.2...



2013-06-17 09.13.3...



2013-06-17 09.13.5...




2013-06-17 09.14.3...



2013-06-17 09.14.3...



2013-06-17 09.15.3...



2013-06-17 09.16.0...



2013-06-17 09.16.2...



2013-06-17 09.17.2...



2013-06-17 09.17.3...



2013-06-17 09.17.4...



2013-06-17 09.17.5...



2013-06-17 09.18.0...



2013-06-17 09.18.2...



2013-06-17 09.18.3...



2013-06-17 09.18.4...



2013-06-17 09.18.5...



2013-06-17 09.18.5...



2013-08-19 09.11.5...



2013-08-19 09.12.0...



2013-08-19 09.12.1...



2013-08-19 09.12.1...



2013-08-19 09.12.3...



2013-08-19 09.12.4...



2013-08-19 09.13.0...



2013-08-19 09.13.1...




2013-08-19 09.13.3...




2013-08-19 09.13.4...



2013-08-19 09.17.2...



2013-08-19 09.38.4...



2013-08-19 09.38.5...



2013-08-19 09.38.5...



2013-08-19 09.39.1...



2013-08-19 09.39.3...



2013-08-19 09.41.5...




2013-08-19 09.42.0...



2013-08-19 09.45.1...



2013-08-19 09.45.3...




2013-08-19 09.45.5...



2013-08-19 09.46.2...



2013-08-19 09.46.4...



2013-08-29 11.14.0...



2013-08-29 11.14.1...



2013-08-29 11.14.4...



2013-08-29 11.14.5...



2013-08-29 11.14.5...



2013-08-29 11.15.2...




2013-08-29 11.15.3...



2013-08-29 11.15.4...



2013-08-29 11.15.4...




2013-08-29 11.16.0...



2013-08-29 11.16.3...



2013-08-29 11.16.4...




2013-08-29 11.16.5...



2013-08-29 11.17.0...



2013-08-29 11.17.0...



2013-08-29 11.17.0...



2013-08-29 11.17.1...



2013-08-29 11.17.2...



2013-08-29 11.17.3...



2013-08-29 11.17.4...




2013-08-29 11.17.56...




2013-08-29 11.17.56...



2013-08-29 11.18.0...




2013-08-29 11.18.2...



2013-08-29 11.18.4...




2013-08-29 11.18.5...



2013-08-29 11.19.0...



2013-08-29 11.19.1...



2013-08-29 11.19.1...



2013-08-29 11.22.0...



2013-08-29 11.22.1...



2013-08-29 11.22.3...



2013-08-29 11.22.3...



2013-08-29 11.22.4...



2013-08-29 11.22.5...



2013-08-29 11.22.5...



2013-08-29 11.23.0...



2013-08-29 11.23.1...



2013-08-29 11.24.2...



2013-08-29 11.24.3...



2013-08-29 11.24.3...



2013-08-29 11.24.3...



2013-08-29 11.24.4...



2013-08-29 11.24.5...



2013-08-29 11.26.1...




2013-08-29 11.26.4...



2013-08-29 11.31.0...



2013-08-29 11.31.2...



2013-08-29 11.32.1...



2013-08-29 11.32.2...




2013-08-29 11.37.2...



APPENDIX K – CAPTAIN KENDRICK HOUSE – MISCELLANEOUS ARTICLES & IMAGES

Captain John Kendrick Maritime Museum

By Jessica Walsh



The Captain John Kendrick Maritime Museum, owned and operated by the Wareham Historical Society, is a fine example of a colonial house and also a museum. All of the rooms contain furnishings and artifacts dating from the 18th and 19th centuries. There are many items that remind the visitors of the ocean. The Captain John Kendrick Museum is a great place to travel back in time!

The Kendrick house, built around 1745, is a gambrel roofed Cape style house. In the interior, every room has a fireplace, and there is a hearth in the keeping room. There are two "good morning" staircases. Shaped like a "Y", they go up, then off to the right and the left. On the second floor there are three rooms, two bedrooms and a storage room. Above these rooms is an attic. Some of the rooms are

decorated with wallpaper, which has been reproduced from original samples. Artifacts, like cranberry scoops, spinning wheels, a whip's handle, ice skates, fabrics, costumes, and antique furniture, such as a marble-topped table, can be seen. The exterior of the John Kendrick Museum is painted golden and brightens the area.

The Kendrick house is also a maritime museum. There is a model of the Ernestina, a sculpture of the Lady Washington, and maritime paintings by local artist Charles Sidney Raleigh. There are also whale oil lamps, a telescope, scrimshaw, whale teeth, hardtack, and paintings of a sea captain and his wife. What better place to have a maritime museum than across the street from the ocean? The Captain John Kendrick Museum is truly a great maritime museum.

The Captain John Kendrick Museum has exhibits with information about the ocean and about life in colonial America. It gives its visitors a feeling of what it was like to live in a colonial house, with its low ceilings and furnishings. It also reminds visitors how much a part of Wareham the ocean is. The Kendrick house is a great place to visit!

The Captain John Kendrick

Maritime Museum


Open July and August

Saturday and Sunday 1 – 4

(with guided tours)

Also open by appointment:

Call Betty Wright at (508) 295-3227




Home of Capt. John Kendrick, who commanded first U.S. trading expedition to China via the Pacific Northwest.

C

I
t

.



Howard



APPENDIX L – PRESERVATION BRIEF 47

MAINTAINING THE EXTERIOR OF SMALL & MEDIUM SIZED HISTORIC BUILDINGS



[Home](#) > [How to Preserve](#) > [Preservation Briefs](#) > 47 Maintaining the Exterior

Some of the web versions of the Preservation Briefs differ somewhat from the printed versions. Many illustrations are new and in color; Captions are simplified and some complex charts are omitted. To order hard copies of the Briefs, see [Printed Publications](#).

PRESERVATION BRIEFS

47

Maintaining the Exterior of Small and Medium Size Historic Buildings

Sharon C. Park, FAIA

[Getting Started](#)

[Maintenance, Schedules and Inspection](#)

[Building Components](#)

[Exterior Walls](#)

[Openings](#)

[Projections](#)

[Foundations and Perimeter Grades](#)

[Summary and References](#)

[Reading List](#)

[Download the PDF](#)



Preservation is defined as "the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property. Work, including preliminary measures to protect and stabilize the property, generally focuses upon the ongoing maintenance and repair of historic materials and features rather than extensive replacement and new construction."¹

Maintenance helps preserve the integrity of historic structures. If existing materials are regularly maintained and deterioration is significantly reduced or prevented, the integrity of materials and workmanship of the building is protected. Proper maintenance is the most cost effective method of extending the life of a building. As soon as a building is constructed, restored, or rehabilitated, physical care is needed to slow the natural process of deterioration. An older building has already experienced years of normal weathering and may have suffered from neglect or inappropriate work as well.

Decay is inevitable but deterioration can accelerate when the building envelope is not maintained on a regular basis. Surfaces and parts that were seamlessly joined when the building was constructed may gradually become loose or disconnected; materials that were once sound begin to show signs of weathering. If maintenance is deferred, a typical response is to rush in to fix what has been ignored, creating additional problems. Work done on a crisis level can favor inappropriate treatments that alter or damage historic material.

There are rewards for undertaking certain repetitive tasks consistently according to a set schedule. Routine and preventive care of building materials is the most effective way of slowing the natural process of deterioration. The survival of historic buildings in good condition is primarily due to regular upkeep and the preservation of historic materials.

Well-maintained properties tend to suffer less damage from storms, high winds, and even small earthquakes. Keeping the roof sound, armatures and attachments such as shutters tightened and secured, and having joints and connections functioning well, strengthens the ability of older buildings to withstand natural occurrences.

Over time, the cost of maintenance is substantially less than the replacement of deteriorated historic features and involves considerably less disruption. Stopping decay before it is widespread helps keep the scale and complexity of work manageable for the owner.

This Preservation Brief is designed for those responsible for the care of small and medium size historic buildings, including owners, property administrators, in-house maintenance staff, volunteers, architects, and maintenance contractors. The Brief discusses the benefits of regular inspections, monitoring, and seasonal maintenance work; provides general guidance on maintenance treatments for historic building exteriors; and emphasizes the importance of keeping a written record of completed work.

Getting Started

Understanding how building materials and construction details function will help avoid treatments that are made in an attempt to simplify maintenance but which may also result in long-term damage. It is enticing to read about “maintenance free” products and systems, particularly waterproof sealers, rubberized paints, and synthetic siding, but there is no such thing as maintenance free when it comes to caring for historic buildings. Some approaches that initially seem to reduce maintenance requirements may over time actually accelerate deterioration.

Exterior building components, such as roofs, walls, openings, projections, and foundations, were often constructed with a variety of functional features, such as overhangs, trim pieces, drip edges, ventilated cavities, and painted surfaces, to protect against water infiltration, ultraviolet deterioration, air infiltration, and pest infestation. Construction assemblies and joints between materials allow for expansion and contraction and the diffusion of moisture vapor, while keeping water from penetrating the building envelope. Older buildings use such features effectively and care must be taken to retain them, avoiding the temptation to reduce air infiltration or otherwise alter them.

Monitoring, inspections, and maintenance should all be undertaken with safety in mind. Besides normal safety procedures, it is important to be cognizant of health issues more commonly encountered with older buildings, such as lead-based paint, asbestos, and bird droppings, and to know when it is necessary to seek professional services (see sidebar).

Original building features and examples of special craftsmanship should be afforded extra care. The patina or aging of historic materials is often part of the charm and character of historic buildings. In such cases, maintenance should avoid attempts to make finishes look new by over-cleaning or cladding existing materials. As with any product that has the potential to harm historic materials, the selection of a cleaning procedure should always involve testing in a discreet location on the building to ensure that it will not abrade, fade, streak, or otherwise damage the substrate (Figure 1).



Figure 1. Maintenance involves selecting the proper treatment and protecting adjacent surfaces. Using painter's tape to mask around a brass doorknocker protects the painted door surface from damage when polishing with chemical compounds. On the other hand, hardware with a patinated finish was not intended to be polished and should simply be cleaned with a damp cloth.

Cautions During Maintenance Work

All maintenance work requires attention to safety of the workers and protection of the historic structure.

Examples include the following:

- Care should be taken when working with historic materials containing lead-based paint. For example, damp methods may be used for sanding and removal to minimize air-borne particles. Special protection is required for workers and appropriate safety measures should be followed.
- Materials encountered during maintenance work, such as droppings from pigeons and mice, can cause serious illnesses. Appropriate safety precautions need to be followed. Services of a licensed contractor should be obtained to remove large deposits from attics and crawlspaces.
- Heat removal of paint involves several potential safety concerns. First, heating of lead-containing paint requires special safety precautions for workers. Second, even at low temperature levels, heat removal of paint runs the risk of igniting debris in walls. Heat should be used only with great caution with sufficient coverage by smoke detectors in work areas. Work periods need to be timed to allow monitoring after completion of paint removal each day, since debris will most often smolder for a length of time before breaking out into open flame. The use of torches, open flames, or high heat should be avoided.
- Many chemical products are hazardous and volatile organic compounds (VOC) are banned in many areas. If allowed, appropriate respirators and other safety precautions are essential for use.
- Personal protection is important and may require the use of goggles, gloves, mask, closed-toed shoes, and a hard hat.
- Electrical service should be turned off before inspecting a basement after a flood or heavy rain, where there is high standing water.

Cyclical Maintenance Checklist (Figure 2)

Cyclic Building Inspection Checklist: Horse Stable			Inspection date: 04/24/05	
Building Feature	Material(s)	Condition Description	Maintenance Action Required	Work Done
ROOF:				
Covering	Clay tile	Two slipped tiles	Reattach tiles	5/4/05
	Painted metal standing seam	Slight corrosion; blistering paint on metal roof section	Sand and repaint area that is peeling	6/8/05
Flashing	Painted metal	Flashing in good condition	N/A	N/A
Gutters/Downspouts	6" half round galvanized metal	Gutter sagging; downspouts OK	Realign gutter and put on new hanger strap	5/4/05
			Flush out downspouts	5/5/05
Chimneys	No masonry chimney	N/A	N/A	N/A
Attachments/Penetrations	Metal vent stack and weathervane	Vent stack hood has some peeling paint; vane OK	Sand and repaint vent stack	6/8/05

Figure 2. All personnel associated with a historic structure need to become acquainted with how existing building features should appear and during their daily or weekly routines look for changes that may occur. This will help augment the regular maintenance inspection that will occur at specified intervals based on seasonal changes, use, and other factors. A segment of an inspection form showing the roof elements of a horse stable is shown. The inspection report should be kept along with the maintenance plan and other material in notebook, file or electronic form

Maintenance Plan, Schedules and Inspection

Organizing related work into a written set of procedures, or a Maintenance Plan, helps eliminate duplication, makes it

easier to coordinate work effort, and creates a system for prioritizing maintenance tasks that takes into account the most vulnerable and character-defining elements.

The first time a property owner or manager establishes a maintenance plan or program, it is advisable to have help from a preservation architect, preservation consultant, and/or experienced contractor. Written procedures should outline step-by-step approaches that are custom-tailored to a building. No matter how small the property, every historic site should have a written guide for maintenance that can be as simple as:

1. Schedules and checklists for inspections;
2. Forms for recording work, blank base plans and elevations to be filled in during inspections and upon completion of work;
3. A set of base-line photographs to be augmented over time;
4. Current lists of contractors for help with complex issues or in case of emergencies;
5. Written procedures for the appropriate care of specific materials, including housekeeping, routine care, and preventive measures;
6. Record-keeping sections for work completed, costs, warranty cards, sample paint colors, and other pertinent material.

This information can be kept in one or more formats, such as a three-ring binder, file folders, or a computer database. It is important to keep the files current with completed work forms to facilitate long-term evaluations and planning for future work (Figure 2).

Proper maintenance depends on an organized plan with work prescribed in manageable components. Regular maintenance needs to be considered a priority both in terms of time allotted for inspections and for allocation of funding.

Maintenance work scheduling is generally based on a variety of factors, including the seriousness of the problem, type of work involved, seasonal appropriateness, product manufacturer’s recommendations, and staff availability. There are other variables as well. For example, building materials and finishes on southern and western exposures will often weather faster than those on northern or eastern exposures. Horizontal surfaces facing skyward usually require greater maintenance than vertical ones; in regions with moderate or heavy rainfall, wood and other materials in prolonged shadow are subject to more rapid decay.

Maintenance costs can be controlled, in part, through careful planning, identification of the amount of labor required, and thoughtful scheduling of work. Maintenance schedules should take into account daily and seasonal activities of the property in order to maximize the uninterrupted time necessary to complete the work. Institutions generally need to budget annually between 2 and 4 percent of the replacement value of the building to underwrite the expense of full building maintenance.² Use of trained volunteers to undertake maintenance can help reduce costs.

Exterior inspections usually proceed from the roof down to the foundation, working on one elevation at a time, moving around the building in a consistent direction. On the interior, the attic, inside surfaces of exterior walls, and crawlspaces or basements should be examined for signs of potential or existing problems with the building envelope.

The following chart lists suggested inspection frequencies for major features associated with the building’s exterior, based on a temperate four-season climate and moderate levels of annual rainfall. For areas of different climate conditions and rainfall, such as in the more arid southwest, the nature of building decay and frequency of inspections will vary. For buildings with certain inherent conditions, heavy use patterns, or locations with more extreme weather conditions, the frequency of inspections should be altered accordingly.

Note: All building features should be inspected after any significant weather event such as a severe rainstorm or unusually high winds.

Survey observations can be recorded on a standardized report form and photographs taken as a visual record. All deficient conditions should be recorded and placed on a written schedule to be corrected or monitored.

INSPECTION FREQUENCY CHART

Feature	Minimum Inspection Frequency	Season
---------	------------------------------	--------

Roof	Annually	Spring or fall; every 5 years by roofer
Chimneys	Annually	Fall, prior to heating season; every 5 years by mason
Roof Drainage	6 months; more frequently as needed	Before and after wet season, during heavy rain
Exterior Walls and Porches	Annually	Spring, prior to summer/fall painting season
Windows	Annually	Spring, prior to summer/fall painting season
Foundation and Grade	Annually	Spring or during wet season
Building Perimeter	Annually	Winter, after leaves have dropped off trees
Entryways	Annually; heavily used entries may merit greater frequency	Spring, prior to summer/fall painting season
Doors	6 months; heavily used entry doors may merit greater frequency	Spring and fall; prior to heating/cooling seasons
Attic	4 months, or after a major storm	Before, during and after wet season
Basement/Crawlspace	4 months, or after a major storm	Before, during and after rain season

Building Components

For purposes of this discussion, the principal exterior surface areas have been divided into five components and are presented in order from the roof down to grade. While guidance for inspection and maintenance is provided for each component, this information is very general in nature and is not indeed to be comprehensive in scope. Examples have been selected to address some typical maintenance needs and to help the reader avoid common mistakes.

Roofs/Chimneys

The roof is designed to keep water out of a building. Thus one of the principal maintenance objectives is to ensure water flows off the roof and into functional gutters and downspouts directly to grade and away from the building—and to prevent water from penetrating the attic, exterior walls, and basement of a building. (Note: Some buildings were designed without gutters and thus assessments must be made as to whether rain water is being properly addressed at the foundation and perimeter grade.) Keeping gutters and downspouts cleared of debris is usually high on the list of regular maintenance activities (Figure 3). Flashing around chimneys, parapets, dormers, and other appendages to the roof also merit regular inspection and appropriate maintenance when needed. The material covering the roof—wood shingles, slate, tile, asphalt, sheet metal, rolled roofing—requires maintenance both to ensure a watertight seal and to lengthen its service life; the type and frequency of maintenance varies with the roofing material. Older chimneys and parapets also require inspection and maintenance. With the exception of cleaning and minor repairs to gutters and downspouts, most roof maintenance work will necessitate use of an outside contractor.

Inspection

The functioning of gutters and downspouts can be safely observed from the ground during rainy weather and when winter ice has collected. Binoculars are a useful tool in helping to identify potential roofing problems from the same safe vantage point. Careful observation from grade helps to identify maintenance needs between close-up inspections by an experienced roofer. Observation from the building interior is also important to identify possible leak locations. When access can be safely gained to the roof, it is important to wear shoes with slip-resistant soles and to use safety ropes. Depending on the nature of the roof, some common conditions of concern to look for are:

- sagging gutters and split downspouts;
- debris accumulating in gutters and valleys;
- overhanging branches rubbing against the roof or gutters
- plant shoots growing out of chimneys;

- slipped, missing, cracked, bucking, delaminating, peeling, or broken roof coverings;
- deteriorated flashing and failing connections at any intersection of roof areas or of roof and adjacent wall;
- bubbled surfaces and moisture ponding on flat or low sloped roofs;
- evidence of water leaks in the attic;
- misaligned or damaged elements, such as decorative cresting, lightning rods, or antennas; and
- cracked masonry or dislodged chimney caps.

Maintenance

- Remove leaves and other debris from gutters and downspouts. Utilize a ladder with a brace device, if necessary, to keep the ladder from crushing the gutter. Use a garden hose to flush out troughs and downspouts. Patch or repair holes in gutters using products such as fiberglass tape and epoxy adhesive in metal gutters. Avoid asphalt compounds since acidic material can cause further deterioration of metal gutters.
- Correct misaligned gutters and adjust, if necessary, so that water flows to drains and does not pond. If gutter edges sag, consider inserting wooden wedges between the fascia board and the back of the gutter to add support. Seal leaking seams or pinholes in gutters and elbows.
- Broom sweep branch or leaf debris away from shingles, valleys, and crickets, particularly around chimneys and dormers.
- Where mechanical equipment is mounted on flat or low-sloped roofs, ensure that access for maintenance can be provided without damaging the roof. Clean out trapped leaves and debris from around equipment base and consider adding a protective walkway for access.



Figure 3. Keeping gutters clean of debris can be one of the most important cyclical maintenance activities. On this small one-story addition, a garden hose is being used to flush out the trough to ensure that the gutter and downspouts are unobstructed. Gutters on most small and medium size buildings can be reached with an extension ladder and a garden hose. Photo: Bryan Blundell.



Figure 4. Damage to roofs often requires immediate attention. As a temporary measure, this damaged roof tile could be replaced with a brown aluminum sheet wedged between the existing tiles. Photo: Chad Randl.

- Remove biological growth where it is causing erosion or exfoliation of roofing. Use low-pressure garden hose water and a natural or nylon scrubbing brush to remove such growth, scraping with a plastic putty knife or similar wood or plastic tool as needed on heavier buildup. Most growth is acidic and while there are products designed to kill spores, such as diluted chlorine bleach, they should be avoided. Even fairly weak formulas can still cause unexpected color changes, efflorescence, or over-splash damage to plantings or surfaces below the roof. Where appropriate, trim adjacent tree branches to increase sunlight on the roof since sunlight will deter further biological growth.
- Re-secure loose flashing at the dormers, chimneys or parapets. Clean out old mortar, lead, lead wool, or fastening material and make sure that flashing is properly inserted into reglet (slot) joints, taking care not to damage the substrate. Avoid installing new step flashing as a single metal component where multiple pieces are required to provide proper waterproofing. Also avoid attaching step flashing with mastic or sealant. Properly re-bed all step flashing. Use appropriate non-ferrous flashing metal or painted metal if needed. Since cap, step, valley,

cricket, and apron flashings each have specific overlap and extension requirements, replacement flashing should match the existing material unless there has been a proven deficiency.

- Repoint joints in chimneys, parapet, or balustrade capping stones using a hydraulic lime mortar or other suitable mortar where the existing mortar has eroded or cracked, allowing moisture penetration. In general, a mortar that is slightly weaker than the adjacent masonry should be used. This allows trapped moisture in the masonry to migrate out through the mortar and not the masonry. Spalled masonry is often evidence of the previous use of a mortar mix that was too hard.
- Use professional services to repair chimneys and caps. Avoid the use of mortar washes on masonry since they tend to crack, allowing moisture to penetrate and promoting masonry spalling. Repoint masonry with a durable mortar that is slightly weaker than the adjacent masonry. Slope the masonry mortar cap to insure drainage away from the flue. If a chimney rain cap is installed, ensure adequate venting and exhaust.

- As a temporary measure, slip pieces of non-corrosive metal flashing under or between damaged and missing roofing units until new slate, shingles, or tile can be attached. Repair broken, missing or damaged roofing units with ones that match. Follow roofing supplier and industry guidance on inserting and attaching replacement units (Figure 4). Avoid using temporary asphalt patches as it makes a proper repair difficult later on.
- For long-term preservation of wooden shingle roofs coated with a preservative, recoat every few years following the manufacturer's recommendations. Be aware of environmental considerations.
- Scrape and repaint selected areas of coated ferrous metal roofing as needed; repaint on a regularly scheduled basis. Ferrous metal roofs can last a long time if painted regularly. Alkyd coatings are generally used on metal roofs; be sure to wash and properly prepare the area beforehand. Environmental regulations may restrict the use of certain types of paints. Apply the coating system in accordance with manufacturer's recommendations. Prepare the surface prior to application to obtain good adhesion with the prime coat. Apply both a prime coat and a topcoat for good bonding and coverage; select primer and topcoat products from the same manufacturer.
- Re-secure loose decorative elements, such as finials and weathervanes. Seek professional advice if decorative elements exhibit considerable corrosion, wood rot, or structural instability. Small surface cracks may benefit from a flexible sealant to keep moisture out; sealants have a limited life and require careful inspection and periodic replacement (Figure 5).




Figure 5. The use of a sealant to close an exposed joint is not always an effective long-term solution. Where this decorative wood element connects to the slate roof, the sealant has failed within a short time and a proper metal flashing collar is being fitted instead. Photo: Bryan Blundell.



Figure 6. Stucco applied to an exterior wall or foundation was intended to function as a watertight surface. Unless maintained, rainwater will penetrate open joints and cracks that may occur over time. A small section of stucco indicates some damage has occurred and a wooden mallet is being used to tap the surface to determine whether the immediate stucco has lost adhesion. Photo: Bryan Blundell.

Exterior Walls

Exterior walls are designed to help prevent water infiltration, control air infiltration, and serve as a barrier for unwanted animals, birds and insects. The primary maintenance objective is to keep walls in sound condition and to prevent water penetration, insect infestation, and needless decay (Figure 6). Depending on the materials and construction methods, walls should have an even appearance, free from unwanted cracks, and should be able to shed excess moisture. Where surfaces are significantly misaligned or where there are bulging wall sections or cracks indicative of potential structural problems, seek professional guidance as to the cause of distress and appropriate corrective measures. Wood-frame construction generally will require more frequent maintenance than buildings constructed of brick, stone, or terra cotta (Figure 7).

Inspections

It is best to inspect walls during dry as well as wet weather. Look for moisture patterns that may appear on the walls after a heavy or sustained rainfall or snow, recording any patterns on elevation drawings or standard recording forms. Monitoring the interior wall for moisture or other potential problems is important as well. Look for movement in cracks, joints, and around windows and doors and try to establish whether movement is seasonal in nature (such as related to shrinkage of wood during dry weather) or signs of an ongoing problem. For moderate size buildings, a ladder or mechanical lift may be necessary, though in some cases the use of binoculars and observations made from windows and other openings will be sufficient. When examining the walls, some common conditions of concern to look for are:

- Misaligned surfaces, bulging wall sections, cracks in masonry units, diagonal cracks in masonry joints, spalling masonry, open joints, and nail popping;
- Evidence of wood rot, insect infestation, and potentially damaging vegetative growth;
- Deficiencies in the attachment of wall mounted lamps, flag pole brackets, signs, and similar items;
- Potential problems with penetrating features such as water spigots, electrical outlets, and vents;

- Excessive damp spots, often accompanied by staining, peeling paint, moss, or mold; and
- General paint problems (Figure 8).

Maintenance

- Trim tree branches away from walls. Remove ivy and tendrils of climbing plants by first cutting at the base of the vine to allow tendrils to die back, and later using a plastic scraper to dislodge debris and an appropriate digging tool to dislodge and remove root systems. Be cautious if using a commercial chemical to accelerate root decay; follow safety directions and avoid contact of chemicals with workers and wall materials.
- Wash exterior wall surfaces if dirt or other deposits are causing damage or hiding deterioration; extend scheduled times for cleaning for cosmetic purposes to reduce frequency (Figure 9). When cleaning, use the gentlest means possible; start with natural bristle brushes and water and only add a mild phosphate-free detergent if necessary. Use non-abrasive cleaning methods and low-pressure water from a garden hose. For most building materials, such as wood and brick, avoid abrasive methods such as mechanical scrapers and high-pressure water or air and such additives as sand, natural soda, ice crystals, or rubber products. All abrasives remove some portion of the surface and power-washing drives excessive moisture into wall materials and even into wall cavities and interior walls. If using a mild detergent, two people are recommended, one to brush and one to prewet and rinse. When graffiti or stains are present, consult a preservation specialist who may use poultices or mild chemicals to remove the stain. If the entire building needs cleaning other than described above, consult a specialist.
- Repoint masonry in areas where mortar is loose or where masonry units have settled. Resolve cause of cracks or failure before resetting units and repointing. Rake out joints by hand, generally avoiding rotary saws or drills, to a depth of 2 ½ times the width of the joint (or until sound mortar is encountered), to make sure that fresh mortar will not pop out. Repointing mortar should be lime-rich and formulated to be slightly weaker than the masonry units and to match the historic mortar in color, width, appearance, and tooling. Off-the-shelf pre-mixed cement mortars are not appropriate for most historic buildings. Avoid use of joint sealants in place of mortar on vertical masonry wall surfaces, as they are not breathable and can lead to moisture-related damage of the adjacent masonry (Figure 10).
- Correct areas that trap unwanted moisture. Damaged bricks or stone units can sometimes be removed, turned around, and reset, or replaced with salvaged units. When using traditional or contemporary materials for patching wood, masonry, metal, or other materials, ensure that the materials are compatible with the substrate; evaluate strength, vapor permeability, and thermal expansion, as well as appearance.
- When patching is required, select a compatible patch material. Prepare substrate and install patch material according to manufacturer's recommendations; respect existing joints. Small or shallow surface defects may not require patching; large or deep surface defects may be better addressed by installation of a dutchman unit than by patching.
- Where a damaged area is too large to patch, consider replacing the section with in-kind material. For stucco and adobe materials, traditional patching formulas are recommended.
- When temporarily removing wood siding to repair framing or to tighten corner boards and loose trim, reuse the existing siding where possible. Consider using stainless steel or high strength aluminum nails as appropriate. Putty or fill nail holes flush with siding prior to repainting. Back-prime any installed wood with one coat of primer and coat end grain that might be exposed with two coats of primer.
- Prepare, prime, and spot paint areas needing repainting. Remember that preparation is the key to a successful long




Figure 7. One of the advantages of wood shingles as a wall covering is that individual shingles that are damaged can easily be replaced. On this highly exposed corner, worn shingles have been selectively replaced to help safeguard against water damage. The new shingles will be stained to match the existing shingles.



Figure 8. The paint on the siding of this south-facing wall needs to be scraped, sanded, primed and repainted. Postponing such work will lead to further paint failure, require greater preparatory costs, and could even result in the need to replace some siding. Photo: Charles Fisher.



Figure 9. To help extend a repainting cycle, dirt and spider webs should be removed before permanent staining occurs. In this case, a natural bristle brush and a soft damp cloth are being used to remove insect debris and refresh the surface appearance.

lasting paint job. Ensure beforehand the compatibility of new and existing paints to avoid premature paint failure. Remove loose paint to a sound substrate; sand or gently rough surface if needed for a good paint bond; wipe clean; and repaint with appropriate primer and topcoats. Follow manufacturer's recommendations for application of coatings, including temperature parameters for paint application. Use top quality coating materials. Generally paint when sun is not shining directly onto surfaces to be painted.

- Remove deteriorated caulks and sealants, clean, and reapply appropriate caulks and sealants using backer rods as necessary. Follow manufacturer's instructions regarding preparation and installation.
- Correct deficiencies in any wall attachments such as awning and flag pole anchors, improperly installed electrical outlets, or loose water spigots.

Openings

Exterior wall openings primarily consist of doors, windows, storefronts, and passageways. The major maintenance objectives are to retain the functioning nature of the opening and to keep in sound condition the connection between the opening and the wall in order to reduce air and water infiltration.

Inspection

Wall openings are typically inspected from inside as well as out. Examinations should include the overall material condition; a check for unwanted water penetration, insect infiltration, or animal entry; and identification of where openings may not be properly functioning. Frames should be checked to make sure they are not loose and to ascertain whether the intersection between the wall and the frame is properly sealed. Secure connections of glazing to sash and between sash and frames are also important. Particular attention should be placed on exposed horizontal surfaces of storefronts and window frames as they tend to deteriorate much faster than vertical surfaces. Inspections should identify:

- loose frames, doors, sash, shutters, screens, storefront components, and signs that present safety hazards;
- slipped sills and tipped or cupped thresholds;
- poorly fitting units and storm assemblies, misaligned frames, drag marks on thresholds from sagging doors and storm doors;
- loose, open, or decayed joints in door and window frames, doors and sash, shutters, and storefronts;
- loose hardware, broken sash cords/chains, worn sash pulleys, cracked awning, shutter and window hardware, locking difficulties, and deteriorated weatherstripping and flashing;
- broken/cracked glass, loose or missing glazing and putty;
- peeling paint, corrosion or rust stains; and
- window well debris accumulation, heavy bird droppings, and termite and carpenter ant damage.

Maintenance

- Replace broken or missing glass as soon as possible; in some cases cracked glass may be repaired using specialty glues. For historic crown glass and early cylinder glass, a conservation approach should be considered to repair limited cracks. Where panes with a distinct appearance are missing, specialty glass should be obtained to match, with sufficient inventory kept for future needs. Avoid using mechanical devices to remove old putty and match historic putty bevels or details when undertaking work.
- Reputty window glazing where putty is deteriorated or missing. Take care in removing putty so as not to crack or break old glass or damage muntins and sash frames. Re-glaze with either traditionally formulated oil putties or modern synthetic ones, making sure to properly bed the glass and secure with glazing points (Figure 11).



Figure 10. Repointing of masonry should usually be approached as repair rather than maintenance work in part because of the need for a skilled mason familiar with historic mortar. In this case, a moisture condition was not corrected and the use of a waterproof coating and off-the-shelf Portland cement mortar trapped water and resulted in further damage to these 19th century bricks. Photo: NPS files

- Clean window glass, door glazing, storefronts, transom prism lights, garage doors, and storm panels using a mild vinegar and water mixture or a non-alkaline commercial window cleaner. Be cautious with compounds that contain ammonia as they may stain brass or bronze hardware elements if not totally removed. When using a squeegee blade or sponge, wipe wet corners with a soft dry cloth. Avoid high-pressure washes.
- Clean handles, locks and similar hardware with a soft, damp cloth. Use mineral spirits or commercial cleaners very sparingly, as repeated use may remove original finishes. Most metal cleaners include ammonia that can streak and stain metal, so it is important to remove all cleaning residue. Polished hardware subject to tarnishing or oxidation, particularly doorknobs, often benefits from a thin coat of paste wax (carnauba), hand buffed to remove extra residue. Avoid lacquer finishes for high use areas, as they require more extensive maintenance. Patinated finishes should not be cleaned with any chemicals, since the subtle aged appearance contributes to the building's character.
- Remove and clean hardware before painting doors and windows; reinstall after the paint has dried.
- Tighten screws in doorframes and lubricate door hinges, awning hardware, garage door mechanisms, window sash chains, and pulleys using a graphite or silicone type lubricant.
- Check weather stripping on doors and windows and adjust or replace as necessary. Use a durable type of weather stripping, such as spring metal or high quality synthetic material, avoiding common brush and bulb or pile weather stripping that require more frequent replacement.
- Adjust steel casement windows as needed for proper alignment and tight fit. Avoid additional weather stripping as this may lead to further misalignment, creating pathways for air and water infiltration.
- Check window sills for proper drainage. Fill cracks in wood sills with a wood filler or epoxy. Follow manufacturer's instructions for preparation and installation. Do not cover over a wood sill with metal panning, as it may trap moisture and promote decay.
- Repair, prime, and repaint windows, doors, frames, and sills when needed. Clean out putty debris and paint chips from windows using a wet paper towel and dispose of debris prior to repair or repainting. Take appropriate additional precautions when removing lead-based paint. Sand and prepare surfaces and use material-specific patching compounds to fill any holes or areas collecting moisture (Figure 12). Avoid leaving exposed wood unpainted for any length of time, as light will degrade the wood surface and lead to premature failure of subsequent paint applications. Immediately prime steel sash after paint is removed and the substrate prepared for repainting.
- Adjust wood sash that bind when operated. Apply beeswax, paraffin, or similar material to tracks or sash runs for ease of movement. If sash are loose, replace worn parting beads. Sash runs traditionally were unpainted between the stop and parting bead; removing subsequent paint applications will often help improve sash operation.
- Correct perimeter cracks around windows and doors to prevent water and air infiltration. Use traditional material or modern sealants as appropriate. If fillers such as lead wool have been used, new wool can be inserted with a thin blade tool, taking care to avoid damage to adjacent trim. Reduce excess air infiltration around windows by repairing and lubricating sash locks so that windows close tightly.
- Remove debris beneath window air conditioning units and ensure that water from units does not drain onto sills or wall surfaces below (Figure 13). Removal of air conditioning units when not in season is recommended.
- Adjust storm panels and clean weep holes; check that weep holes at the bottom of the panels are open so water will not be trapped on the sill. Exterior applied storm windows are best attached using screws and not tightly adhered with sealant. Use of sealant makes storm units difficult to remove for maintenance and can contribute to moisture entrapment if weep holes become clogged.
- Remove weakened or loose shutters and store for later repair. Consider adding a zinc or painted metal top to shutters as a protective cap to cover the wood's exposed end grain. This will extend the life of the shutters.



Figure 11. Glazing putty should be maintained in sound condition to prevent unwanted air infiltration and water damage. New glazing putty should be pulled tight to the glass and edge of the wood, creating a clean bevel that matches the historic glazing



Figure 12. Good surface preparation is essential for long lasting paint. Scraping loose paint, filling nail holes and cracks, sanding, and wiping with a damp cloth prior to repainting are all important steps whether touching up small areas or repainting an entire feature. Always use a manufacturer's best quality paint. Windows and shutters may need repainting every five to seven years, depending on exposure and climate.



Figure 13. Window air conditioning units can cause damage to surfaces below when condensation drips in an uncontrolled manner. Drip extension tubes can sometimes be added to direct the discharge.

Contracting Maintenance and Repair Work

Many contractors are very proficient in using modern construction methods and materials; however, they may not have the experience or skill required to carry out maintenance on historic buildings. The following are tips to use when selecting a contractor to work on your historic building:

1. Become familiar with work done on similar historic properties in your area so that you can obtain names of possible preservation contractors.
 2. Be as specific as possible in defining the scope of work you expect to undertake.
 3. Ask potential contractors for multiple references (three to five) and visit previous work sites. Contact the building owner or manager and ask how the job proceeded; if the same work crew was retained from start to finish; if the workers were of a consistent skill level; whether the project was completed in a reasonable time; and whether the person would use the contractor again.
 4. Be familiar with the preservation context of the work to be undertaken. Use the written procedures in your maintenance plan to help define the scope of work in accordance with preservation standards and guidelines. Always request that the gentlest method possible be used. Use a preservation consultant if necessary to ensure that the work is performed in an appropriate manner.
 5. Request in the contract proposal a detailed cost estimate that clearly defines the work to be executed, establishes the precautions that will be used to protect adjoining materials, and lists specific qualified subcontractors, if any, to be used.
 6. Insure that the contractor has all necessary business licenses and carries worker compensation.
-

Projections

Numerous projections may exist on a historic building, such as porches, dormers, skylights, balconies, fire escapes, and breezeways. They are often composed of several different materials and may include an independent roof. Principal maintenance objectives include directing moisture off these features and keeping weathered surfaces in good condition. Secondary projections may include brackets, lamps, hanging signs, and similar items that tend to be exposed to the elements.

Inspection

In some cases, projections are essentially independent units of a building and so must be evaluated carefully for possible settlement, separation from the main body of the building, and materials deterioration. Some electrical features may require inspection by a electrician or service technician. Common conditions of concern to look for are:

- damaged flashing or tie-in connections of projecting elements;
- misaligned posts and railings;
- deteriorated finishes and materials, including peeling paint, cupped and warped decking, wood deterioration, and hazardous steps;
- evidence of termites, carpenter ants, bees, or animal pests (Figure 14);
- damaged lamps, unsafe electrical outlets or deteriorated seals around connections;
- loose marker plaques, sign, or mail boxes; and
- rust and excessive wear of structural, anchorage, and safety features of balconies and fire escapes.

Maintenance

- Selectively repair or replace damaged roofing units on porches and other projections. Ensure adequate drainage away from the building. Repair flashing connections as needed; clean and seal open joints as appropriate.
- Secure any loose connections, such as on porch rails or fire escapes.
- Maintain ferrous metal components by following manufacturer's recommendation for cleaning and repainting. Remove rust and corrosion from porch handrails, balconies, fire escapes, and other metal features; prepare, prime, and repaint using a corrosion-inhibitive coating system. Apply new primer before new corrosion sets in, followed by new topcoat. Take appropriate safety measures when dealing with existing lead-based paint and in using corrosion-removal products (Figure 15).
- Reattach loose brackets, lamps, or signs. With electrical boxes for outlets or lighting devices, ensure that cover plates are properly sealed. Prime and paint metal elements as needed.
- Keep porch decks and steps free from dust, dirt, leaf debris, and snow as soon as it accumulates using a broom or plastic blade shovel.
- Repair areas of wood decay or other damage to railings, posts, and decorative elements. Repair with wood dutchman, wood putty, or epoxy filler, as appropriate; replace individual elements as needed. Prime and repaint features when necessary and repaint horizontal surfaces on a more frequent basis.
- Sand and repaint porch floorboards to keep weather surfaces protected. The exposed ends of porch floorboards are especially susceptible to decay and may need to be treated every year or two.
- Carefully cut out damaged or buckled porch flooring and replace with wood to match. Back-prime new wood that is being installed; treat end grain with wood preservative and paint primer. Ensure that new wood is adequately kiln or air-dried to avoid shrinkage and problems with paint adherence.
- Repair rotted stair stringers; adjust grade or add stone pavers at stair base to keep wooden elements from coming into direct contact with soil.
- Consider durable hardwoods for replacement material where beading, chamfering, or other decorative work is required in order to match existing features being replaced. Although appropriate for certain applications, pressure treated lumber is hard to tool and may inhibit paint adherence if not allowed to weather prior to coating application.




Figure 14. When inspecting connections between projections and the main building, look for areas where birds, bees and pests may enter or nest. Birds have been nesting in this porch roof and the area is being cleaned of their debris. Where an opening exists, it may be necessary to cover it with a trim piece, screening, or sealant. Photo: Bryan Blundell



Figure 15. Metal projecting elements on a building, such as sign armatures and railings, are easily subject to rust and decay. Proper surface preparation to remove rust is essential. Special metal primers and topcoats should be use

- Clean out any debris from carpenter bees, ants, termites, and rodents, particularly from under porches. Replace damaged wood and add screening or lattice to discourage rodents. Consider treating above ground features with a borate solution to deter termites and wood rot and repaint exposed surfaces.

Foundations and Perimeter Grades

The foundation walls that penetrate into the ground, the piers that support raised structures, and the ground immediately around a foundation (known as grade) serve important structural functions. To help sustain these functions, it is important that there is good drainage around and away from the building. The maintenance goal is to prevent moisture from entering foundations and crawl spaces and damaging materials close to the grade, and to provide ventilation in damp areas.

Inspection

Inspections at the foundation should be done in conjunction with the inspection of the downspouts to ensure that water is being discharged a sufficient distance from the building perimeter to avoid excessive dampness in basements or crawl spaces. In addition, crawl spaces should be adequately vented to deter mold and decay and should be screened or otherwise secured against animals. Look for:

- depressions or grade sloping toward the foundation; standing water after a storm;
- material deterioration at or near the foundation, including loss of mortar in masonry, rotting wood clapboards, or settlement cracks in the lower sections of wall;
- evidence of animal or pest infestation;
- vegetation growing close to the foundation, including trees, shrubs and planting beds;
- evidence of moisture damage from lawn and garden in-ground sprinkler systems;
- evidence of moss or mold from damp conditions or poorly situated downspout splash blocks (Figure 16); and
- blocked downspout drainage boots or clogged areaway grates.

Maintenance

- Remove leaves and other debris from drains to prevent accumulation. Detach drain grates from paved areas and extract clogged debris. Flush with a hose to ensure that there is no blockage. Use a professional drain service to clear obstructions if necessary.
- Conduct annual termite inspections. Promptly address termite and other insect infestations. Use only licensed company for treatment where needed.
- Keep the grade around the foundation sloping away from the building. Add soil to fill depressions particularly around downspouts and splash blocks. Make sure that soil does not come too close to wooden or metal elements. A 6" separation between wooden siding and the grade is usually recommended.
- Avoid use of mulching material immediately around foundations as such material may promote termite infestation, retain moisture or change existing grade slope.
- Reset splash blocks at the end of downspouts or add extender tubes to the end of downspouts as necessary (Figure 17).
- Lubricate operable foundation vent grilles to facilitate seasonal use; paint as needed.
- Manage vegetation around foundations to allow sufficient air movement for wall surfaces to dry out during damp periods. Trim plantings and remove weeds and climbing vine roots. Be careful not to scar foundations or porch piers with grass or weed cutting equipment. If tree roots appear to be damaging a foundation wall, consult an engineer as well as a tree company.
- Wash off discoloration on foundations caused by splash-back, algae, or mildew. Use plain water and a soft natural or nylon bristle brush. Unless thoroughly researched and tested beforehand on a discreet area of the wall, avoid chemical



Figure 16. This chronically wet area has a mildew bloom brought on by heat generated from the air-conditioning condenser unit. The dampness could be caused by a clogged roof gutter, improper grading, or a leaking hose bibb.

products that may discolor certain types of stone. If cleaning products are used, test beforehand in a discreet area; and avoid over splash to plantings and adjacent building materials.

- Selectively repoint unit masonry as needed. Follow guidance under the wall section in regard to compatible mix, appearance, and texture for pointing mortar.
 - Avoid using salts for de-icing and fertilizers with a high acid or petro-chemical content around foundations, as these materials can cause salt contamination of masonry. Use sand or organic materials without chloride additives that can damage masonry. Where salt is used on icy walks, distribute it sparingly and sweep up residual salt after walks have dried.
 - Use snow shovels and brooms to clean snow from historic paths and walkways. Avoid blade-type snow removers as they may chip or abrade cobblestones, brick, or stone paving. Note that use of steel snow removal tools in areas where salt-containing snow melters are used may result in rust staining from steel fragments left on the paving.
-

Sealants and Caulks

Using sealants and caulks has become a familiar part of exterior maintenance today. As the use of precision joinery and certain traditional materials to render joints more weathertight has waned in recent years, caulks and more often elastomeric sealants are used to seal cracks and joints to keep out moisture and reduce air infiltration. Where cracks and failing joints are indicators of a serious problem, sealants and caulks may be used as a temporary measure. In some cases they may actually exacerbate the existing problem, such as by trapping moisture in adjacent masonry, and lead to more costly repairs.

Manufacturer's recommendations provide instructions on the proper application of caulks and sealants. Special attention should be placed on ensuring that the subsurface or joint is properly prepared and cleaned. Backer rods may be necessary for joints or cracks. Tooling of the caulk or sealant is usually necessary to ensure contact with all edge surfaces and for a clean and consistent appearance.

Caulks generally refer to older oil resin-based products, which have relatively limited life span and limited flexibility. Contemporary elastomeric sealants are composed of polymer synthetics. Elastomeric sealants are more durable than caulks and have greater flexibility and wider application. Caulks and sealants can become maintenance problems, as they tend to deteriorate faster than their substrates and must be replaced periodically as a part of cyclical maintenance of the structure.

The selection criteria for caulks and sealants include type of substrate, adhesion properties, size and configuration of joint, intended appearance/color and paintability, movement characteristics, and service life. Both one-part and two-part sealants are available; the latter require mixing as part of the application process. Sealants are commonly used for a variety of places on the exterior of a building such as around windows and doors, at interfaces between masonry and wood, between various wood features or elements, and at attachments to or through walls or roofs, such as with lamps, signs, or exterior plumbing fixtures. Their effectiveness depends on numerous factors including proper surface preparation and application. Applications of sealants and caulks should be examined as part of routine maintenance inspection, irrespective of their projected life expectancy.

Installation of caulks and sealants often can be undertaken by site personnel. For large and more complex projects, a contractor experienced in sealant installation may be needed. In either case, the sealant manufacturer should be consulted on proper sealant selection, preparation, and installation procedures.

Summary and References

Maintenance is the most important preservation treatment for extending the life of a historic property. It is also the most cost effective. Understanding the construction techniques of the original builders and the performance qualities of older building materials, using traditional maintenance and repair methods, and selecting in-kind materials where replacements are needed will help preserve the building and its historic character.

Maintenance can be managed in small distinct components, coordinated with other work, and scheduled over many years to ensure that materials are properly cared for and their life span maximized. A written maintenance plan is the most effective way to organize, schedule, and guide the work necessary to properly care for a historic building. The maintenance plan should include a description of the materials and methods required for each task, as well as a schedule

for work required for maintenance of different building materials and components.

Historic house journals, maintenance guides for older buildings, preservation consultants, and preservation maintenance firms can assist with writing appropriate procedures for specific properties. Priorities should be established for intervening when unexpected damage occurs such as from broken water pipes or high winds. Worker safety should always be paramount. When work is beyond the capabilities of in-house personnel and must be contracted, special efforts should be made to ensure that a contractor is both experienced in working with historic buildings and utilizes appropriate preservation treatments.

A well-maintained property is a more valuable property and one that will survive as a legacy for generations to come.

Endnotes

1. *The Secretary of the Interior's Standards for the Treatment of Historic Properties*. Washington, D.C.: U.S. Department of the Interior, National Park Service, 1995.

2. Committee on Advanced Maintenance Concepts for Buildings et al, *Committing to the Cost of Ownership: Maintenance and Repair of Public Buildings*, Washington, D.C.: National Academy Press, 1990.

Acknowledgements

Sharon C. Park FAIA, is the former Chief of Technical Preservation Services, Heritage Preservation Services, National Park Service, in Washington, D.C. and currently is the Associate Director for Architectural History and Historic Preservation, Smithsonian Institution.

The author wishes to thank Mike Seibert of the National Park Service for research on the project and the development of the charts; and Lauren Burge, AIA, of the firm of Chambers, Murphy & Burge, and Michael Emerick, AIA, for sharing their expertise on maintenance and providing early guidance. Thanks go to Deborah Slaton of the firm of Wiss, Janney, Elstner Associates, Inc., for her insightful contributions and also to Rebecca Stevens of the National Park Service, Dominique Hawkins, AIA, of Preservation Design Partnership, J. Bryan Blundell of Dell Corporation, and Michael Scheffler and Kenneth Itle of Wiss, Janney, Elstner Associates, Inc. Also gratefully acknowledge for their assistance in the technical review and editing of this publication are Charles E. Fisher, Anne E. Grimmer, and Chad Randl of the National Park Service's Technical Preservation Services, and former staff Kay D. Weeks. Numerous other National Park Service staff and partners commented on the manuscript and made substantial contributions.

This publication has been prepared pursuant to the National Historic Preservation Act, as amended, which directs the Secretary of the Interior to develop and make available information concerning historic properties. Comments about this publication should be made to: Charles Fisher, Technical Publications Program Manager, Technical Preservation Services-2255, National Park Service, 1849 C Street, NW, Washington, D.C. 20240. This publication is not copyrighted and can be reproduced without penalty. Normal procedures for credit to the author and the National Park Service are appreciated. Unless otherwise noted, photographs in this Brief are by Sharon C. Park, FAIA. Except for the author's photos, the photographs used in this publication may not be used to illustrate other publications without permission of the owner.

June 2007



Figure 17. Extending downspouts at their base is one of the basic steps to reduce dampness in basements, crawl spaces and around foundations. Extensions should be buried, if possible, for aesthetics, ease of lawn care, and to avoid creating a tripping hazard. Photo: NPS files.

Reading List

Chambers, J. Henry. *Cyclical Maintenance for Historic Buildings*. Washington, D.C.: National Park Service, 1976,

Fisher, Charles E. and Hugh C. Miller, eds. *Caring For Your Historic House*. New York, NY: Harry N. Abrams, Inc., 1998.

Fisher, Charles E., Deborah Slaton, and Rebecca Shiffer, eds. *Window Rehabilitation Guide for Historic Buildings*. Washington, D.C.: Historic Preservation Education Foundation, 1997.

Fram, Mark. *Well-Preserved: The Ontario Heritage Foundation's Manual of Principles and Practice for Architectural*

Conservation. Erin, Ontario: The Boston Mills Press, 1988.

Gayle, Margot, David W. Look, AIA, and John G. Waite, FAIA. *Metals in America's Historic Buildings: Use and Preservation Treatments*. Washington, D.C.: National Park Service, 1992.

Grimmer, Anne E. *Keeping It Clean: Removing Exterior Dirt, Paint, Stains & Graffiti from Historic Masonry Buildings*. Washington, D.C.: National Park Service, 1988.

Jester, Thomas C., ed. *Twentieth Century Building Materials: History and Conservation*. New York, NY: McGraw-Hill, 1995.

Leeke, John C. *Practical Restoration Reports Compendium*. Portland, ME: Historic HomeWorks, 2005.

London, Mark. *Masonry: How to Care for Old and Historic Brick and Stone*. Washington, D.C.: The Preservation Press, 1988.

Preservation Briefs. Washington, D.C.: National Park Service. The collection of Preservation Briefs assist owners and developers of historic buildings in recognizing and resolving common preservation, maintenance and repair problems.

Preservation Tech Notes. Washington, D.C.: National Park Service. The collection of Preservation Tech Notes provides guidance and case studies on the care and maintenance of historic structures.

Yapp, Bob and Rich Binsacca. *About Your House with Bob Yapp*. San Francisco, CA: KQED Books & Tapes, 1997.
